

**Aviation Safety Investigation Report
199701793**

**Amateur Built Aircraft
MM-II**

01 June 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199701793 **Occurrence Type:** Accident
Location: 9km S Marulan
State: NSW **Inv Category:** 4
Date: Sunday 01 June 1997
Time: 1205 hours **Time Zone** EST
Highest Injury Level: Minor
Injuries:

	Fatal	Serious	Minor	None	Total
Crew	0	0	0	1	1
Ground	0	0	0	0	0
Passenger	0	0	1	0	1
Total	0	0	1	1	2

Aircraft Manufacturer: Amateur Built Aircraft
Aircraft Model: MM-II
Aircraft Registration: VH-MUT **Serial Number:** V104
Type of Operation: Non-commercial Pleasure/Travel
Damage to Aircraft: Substantial
Departure Point: Maryborough VIC
Departure Time: 0915 EST
Destination: Marulan NSW

Crew Details:

Role	Class of Licence	Hours on	
		Type	Hours Total
Pilot-In-Command	Private	230.0	800

Approved for Release: Thursday, September 11, 1997

The pilot of the Bushby Mustang aircraft reported that he was conducting a landing on a private airstrip at the conclusion of a travel flight. During the flare, the aircraft contacted the ground heavier than normal on a soft patch on the runway. The nose wheel broke off and the aircraft overturned. The pilot egressed the aircraft without injury and, with the assistance of onlookers, extricated the passenger.

