Aviation Safety Investigation Report 199702820

Britten Norman Ltd Islander

21 August 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199702820		Occurrence Ty	pe: Accident		
Gan Gan, (AL	A)				
NT		Inv Category:	4		
Thursday 21 A	August 1997	7			
1500 hours		Time Zone	CST		
Highest Injury Level: None					
BN-2A-26 VH-LHA Charter Substantial Gove NT 1430 CST	Passenger		856		
	NT Thursday 21 A 1500 hours None er: Britten Norr BN-2A-26 : VH-LHA Charter Substantial Gove NT 1430 CST	Gan Gan, (ALA) NT Thursday 21 August 1997 1500 hours None er: Britten Norman Ltd BN-2A-26 : VH-LHA Charter Passenger Substantial Gove NT	Gan Gan, (ALA) NT Inv Category: Thursday 21 August 1997 1500 hours Time Zone None er: Britten Norman Ltd BN-2A-26 : VH-LHA Serial Number: Charter Passenger Substantial Gove NT 1430 CST		

**Crew Details:** 

	Hours on		
Role	<b>Class of Licence</b>	Туре Но	urs Total
Pilot-In-Command	Commercial	59.3	1380

Approved for Release: Friday, September 5, 1997

During the approach to land, just prior to crossing the runway end, the right main gear struck an earth mound. The gear leg was damaged by the impact. The mound, about three metres short of the 800 metre runway, was about 25 cm high and not easily seen from the approach path. The wind was light and there were no gusts or turbulence.