Aviation Safety Investigation Report 199702913

Israel Aircraft Industries Ltd Astra

05 September 1997

Aviation Safety Investigation Report 199702913

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199702913

Occurrence Number: 199702913 Occurrence Type: Incident

Location: 56km SSW Brisbane, Aerodrome

State: QLD **Inv Category:**

Friday 05 September 1997 Date:

1140 hours Time Zone **EST** Time:

Highest Injury Level: None

Aircraft Manufacturer: Israel Aircraft Industries Ltd

Aircraft Model: 1125

Aircraft Registration: VH-FIS **Serial Number:** 045

Type of Operation: Non-commercial Civil Aviation Authority

Damage to Aircraft:

Departure Point: Brisbane Qld 1025 EST **Departure Time: Destination:** Brisbane Qld

Approved for Release: Friday, September 12, 1997

The aircraft was incorrectly co-ordinated whilst transiting Amberley military CTR. Amberley ATC are required to co-ordinate an estimate for Brisbane for traffic transiting their airspace for landing at Brisbane. The pilot is then assigned a standard transfer level of 4,000 ft. prior to his transfer to Brisbane approach.

The first co-ordination from Amberley in this case, was an attempt to handoff FIS to Brisbane departures when the aircraft was west of Amberley at flight level 150. The departures controller accepted the aircraft to avoid delays. The aircraft continued on an east/ south-easterly heading from Amberley and entered approach south's airspace without co-ordination from Amberley. The pilot eventually contacted departures, and was turned back into the departure controller's airspace for processing for a right circuit on runway 19. There was no breakdown in separation.