Aviation Safety Investigation Report 199703606

Cessna Aircraft Company Skyhawk

27 October 1997

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report 199703606

Occurrence Number:	199703606	Occurrence Type	Accident	
Location:	Maitland, (ALA)			
State:	NSW	Inv Category:	4	
Date:	Monday 27 October 1997	,		
Time:	1200 hours	Time Zone	ESuT	
Highest Injury Level: None				
Aircraft Manufacture Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	er: Cessna Aircraft Compa 172P VH-RNL Instructional Solo Substantial Maitland NSW 1145 ESuT Maitland NSW	ny Serial Number:	17276511	

Crew Details:

	Hours on		
Role	Class of Licence	Type Hour	s Total
Pilot-In-Command	Student	9.0	68

Approved for Release: Friday, April 3, 1998

The student pilot was conducting solo crosswind circuits in a Cessna 172, on runway 23 at Maitland NSW. During a landing sequence, the aircraft touched down heavily and bounced.

The student then used an inappropriate recovery technique that resulted in a second heavy touchdown on the nosewheel. The propeller, cabin floor and firewall suffered damage as a result of the impact.