Aviation Safety Investigation Report 199703692

Burkhart Grob Flugzeugbau G-115

18 October 1997

Aviation Safety Investigation Report 199703692

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199703692 Occurrence Type: Accident

Location: Parafield, Aerodrome

State: SA Inv Category: 4

Date: Saturday 18 October 1997

Time: 1437 hours **Time Zone** CST

Highest Injury Level: None

Aircraft Manufacturer: Burkhart Grob Flugzeugbau

Aircraft Model: G-115

Aircraft Registration: VH-TGT Serial Number: 8071

Type of Operation: Instructional Solo

Damage to Aircraft: Substantial **Departure Point:** Parafield SA

Departure Time:

Destination: Parafield SA

Crew Details:

Role Class of Licence Type Hours Total
Pilot-In-Command Student 53.6 54

Approved for Release: Friday, April 3, 1998

The pilot of a Grob 115 aircraft was conducting a series of circuits after returning from a solo flight to the training area. During the second touch and go the pilot lost directional control. The aircraft veered left and departed the runway, incurring substantial damage as it passed through a ditch. The pilot was uninjured and vacated the aircraft without assistance.