Aviation Safety Investigation Report 199703693

Amateur Built Aircraft Cassutt

10 November 1997

Aviation Safety Investigation Report 199703693

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199703693

Occurrence Number: 199703693 Occurrence Type: Incident

Location: Camden, Aerodrome

Inv Category: State: NSW

Date: Monday 10 November 1997

Time: 1725 hours **Time Zone ESuT**

Highest Injury Level: None

Aircraft Manufacturer: Amateur Built Aircraft

Aircraft Model: ШМ

VH-MXA Aircraft Registration: **Serial Number:** N77

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Minor

Departure Point: Camden NSW **Departure Time:** 1700 ESuT **Destination:** Camden NSW

Crew Details:

Hours on

Role	Class of Licence	Type Hours Total
Pilot-In-Command	Private	97

Approved for Release: Friday, April 3, 1998

A Cassuit Racer had completed a short flight in the Camden area. The pilot reported loosing directional control on touch down, following a normal approach and flare. The aircraft nosed over during the accident sequence, causing damage to the lower engine cowl and propeller.

The pilot had recently purchased the aircraft and this was his first flight on type. As it is a single seat aircraft, he was completing a self-endorsement under the supervision of another pilot.