**Aviation Safety Investigation Report 199703986** 

**Burkhart Grob Flugzeugbau G-115** 

**03 December 1997** 

## Aviation Safety Investigation Report 199703986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

## **Aviation Safety Investigation Report**

199703986

Occurrence Number: 199703986 Occurrence Type: Accident

**Location:** Parafield, Aerodrome

**Inv Category:** State: SA

Date: Wednesday 03 December 1997

Time: 1525 hours **Time Zone CSuT** 

Highest Injury Level: None

Aircraft Manufacturer: Burkhart Grob Flugzeugbau

Aircraft Model: G-115

**Aircraft Registration:** VH-TGY Serial Number: 8083

**Type of Operation:** Instructional Solo

**Damage to Aircraft:** Substantial **Departure Point:** Parafield SA **Departure Time:** 1520 CSuT **Destination:** Parafield SA

**Crew Details:** 

Hours on

Role	<b>Class of Licence</b>	Type Hour	s Total
Pilot-In-Command	Student	33.8	40

**Approved for Release:** Friday, April 3, 1998

The pilot of a Grob 115 aircraft was conducting solo circuits from runway 21L at Parafield. The pilot reported difficulty in maintaining directional control of the aircraft during the first landing flare and attempted to go around. However, the aircraft crash landed to the left of the runway and was substantially damaged. The pilot, who was uninjured, vacated the aircraft without assistance.