Aviation Safety Investigation Report 199600352

Cessna Aircraft Company Cessna Skyhawk

04 February 1996

Aviation Safety Investigation Report 199600352

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199600352

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199600352 Occurrence Type: Accident

Location: Merimbula, Aerodrome

State: NSW Inv Category:

Date: Sunday 04 February 1996

Time: 1045 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172M

Aircraft Registration: VH-WTY Serial Number: 17263172

Type of Operation: Instructional Dual

Damage to Aircraft: Substantial

Departure Point: Merimbula NSW **Departure Time:** 1000 ESuT

Destination: Merimbula NSW

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours Total	
Pilot-In-Command	Commercial	60.0	790

Approved for Release: Wednesday, April 10, 1996

The instructor pilot reported that the aircraft was conducting dual training circuits with a student pilot. The student was having problems judging the landing flare and touch-down. On the third circuit the aircraft ballooned in the flare. A wind gust lifted the right wing causing the aircraft to diverge left of the runway. The left wing tip then struck the runway and the aircraft came to a stop.