Aviation Safety Investigation Report 199600879

Cessna Aircraft Company U206G

19 March 1996

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199600879		Occurrence Type:	Accident
Location:	Mabuiag, (ALA	.)		
State:	QLD		Inv Category:	4
Date:	Suesday 19 March 1996			
Time:	1830 hours		Time Zone	EST
Highest Injury Level:	None			
Aircraft Manufacturer Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	U206G VH-MZH	Passenger QLD	Serial Number	•• U20603602
	8	•		

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours	Total
Pilot-In-Command	Commercial	31.5	415

Approved for Release: Wednesday, October 9, 1996

The pilot reported that all indications were normal during the pre-landing checks. After landing, the brakes were applied but there was no pressure in the left brake. The pilot then initiated a ground loop to the right as speed and distance remaining were inadequate for a go-around.

During the ground loop as the aircraft was sliding sideways across the grass, the left main wheel entered a depression. The sudden stop caused damage to the left wing and main wheel, as well as the nose gear and propeller. All occupants exited the aircraft safely.