Aviation Safety Investigation Report 199603025

Boeing Co B747

21 September 1996

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199603025	Occurrence Type:	Incident	
Location:	Brisbane, Aerodrome			
State:	QLD	Inv Category:	4	
Date:	Saturday 21 September 1990	5		
Time:	1241 hours	Time Zone	EST	
Highest Injury Level:	None			
Aircraft Manufacturer: Aircraft Model: Aircraft Registration:	Boeing Co 747-200 HS-TGS			Serial Number:
Type of Operation:	Air Transport High Capa Scheduled	city International Pas	ssenger	
Damage to Aircraft:	Minor			
Departure Point:	Sydney			
Departure Time:	1035 EST			
Destination:	Brisbane			

Approved for Release: Monday, September 23, 1996

When the aircraft arrived in Brisbane, ground engineers noticed that the left number 11 leading edge flap was missing, and that there was slight damage to the number two engine core cowl. No evidence was found to indicate the primary failure point. A new flap was fitted and the aircraft was dispatched the next day.