Aviation Safety Investigation Report 199603044

Cessna Aircraft Company Skyhawk

23 September 1996

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199603044	Occurrence Type:	Accident
Location:	Charleville, Aerodrome		
State:	QLD	Inv Category:	4
Date:	Monday 23 September 1996	5	
Time:	1315 hours	Time Zone	EST
Highest Injury Level:	None		
Aircraft Manufacture Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	 er: Cessna Aircraft Company 172N VH-EIB Non-commercial Busines Substantial Quilpie QLD 1215 EST Charleville QLD 	Serial Number:	17271742

Crew Details:

	Hours on		
Role	Class of Licence	Туре Нои	irs Total
Pilot-In-Command	Private	1500.0	1500

Approved for Release: Thursday, September 26, 1996

The pilot reported that he had flown a normal circuit and approach to land on runway 30. He did not monitor the airspeed adequately on the approach, with the result that the aircraft began to stall at about 10 feet above the runway. Power was applied to correct the descent, however the aircraft "ballooned" and then landed heavily. When the pilot taxied the aircraft off the runway he thought the nose wheel tyre was deflated.

Post flight examination found that the tie down ring on the underside of the rear fuselage had broken off. The nose landing gear assembly was badly damaged, with sheared rivets at the top of the leg casting, and the engine firewall was buckled. The right side of the nose wheel fork had spread and was abraded by contact with the runway surface.

In describing the event the pilot insisted that it be called an act of "gross stupidity".