Aviation Safety Investigation Report 199604202

Piper Aircraft Corp Tomahawk

22 December 1996

Aviation Safety Investigation Report 199604202

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199604202 Occurrence Type: Accident

Location: Bankstown, Aerodrome

State: NSW Inv Category: 4

Date: Sunday 22 December 1996

Time: 0850 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-38-112

Aircraft Registration: VH-FTX Serial Number: 38-79A0268

Type of Operation: Instructional Solo

Damage to Aircraft: Substantial

Departure Point: Bankstown. NSW

Departure Time: 0845 ESuT

Destination: Bankstown. NSW

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours	Total
Pilot-In-Command	Student	18.0	18

Approved for Release: Monday, December 23, 1996

The student pilot was carrying out his second solo flight, after a dual check. The aircraft was observed to bounce during landing and porpoise along runway 29 L for a short distance before the nose landing gear collapsed. The aircraft slid to a halt on the edge of the runway.