Aviation Safety Investigation Report 199500425

Cessna Aircraft Company Skywagon

17 February 1995

Aviation Safety Investigation Report 199500425

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199500425 Occurrence Type: Accident

Location: Bushy Lagoon

State: QLD Inv Category: 4

Date: Friday 17 February 1995

Time: 0704 hours **Time Zone** EST

Highest Injury Level: Minor

Injuries:

	Fatal	Serious	Minor	None	Total
Crew	0	0	0	1	1
Ground	0	0	0	0	0
Passenger	0	0	1	1	2
Total	0	0	1	2	3

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: A185F

Aircraft Registration: VH-EGB Serial Number: 18503218

Type of Operation: Charter Passenger

Damage to Aircraft: Substantial

Departure Point: Brampton Island QLD

Departure Time: 0625 EST

Destination: Bushy Lagoon QLD

Crew Details:

		Hours on		
Role	Class of Licence	Type Ho	urs Total	
Pilot-In-Command	Senior Commercial	3000.0	16500	

Approved for Release: Thursday, April 13, 1995

The amphibian aircraft landed on relatively smooth water in a lagoon. As soon as the floats touched the water the aircraft slewed to the left, nosed into the water, and turned over. The aircraft came to rest upside down in about three feet of water. The occupants evacuated the aircraft within half a minute and the pilot activated an emergency beacon. A helicopter responding to the emergency arrived at the scene at about 0940.

Visual inspection of the aircraft after the accident revealed that the left main gear was extended. The pilot stated that he had the correct gear-up indications before landing. An inspection of the aircraft did not reveal any reason for the extended left main gear.

One passenger received minor injuries when fuel affected skin on her legs whilst standing in fuel contaminated sea water.