Aviation Safety Investigation Report 199500748

Avtech Pty Ltd JABIRU ST

16 March 1995

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199500748	Occurrence Type:	Accident
Location:	Archerfield		
State:	QLD	Inv Category:	4
Date:	Thursday 16 March 1995		
Time:	1515 hours	Time Zone	EST
Highest Injury Level:	None		

Aircraft Manufacturer:	Avtech Pty Ltd	
Aircraft Model:	JABIRU ST	
Aircraft Registration:	VH-SSC	Serial Number: ST 0002
Type of Operation:	Instructional Dual	
Damage to Aircraft:	Substantial	
Departure Point:	Archerfield QLD	
Departure Time:	1300 EST	
Destination:	Archerfield QLD	

Crew Details:

	Hours on		
Role	Class of Licence	Туре Но	urs Total
Pilot-In-Command	Commercial	50.0	6000

Approved for Release: Friday, March 8, 1996

Sequence of Events.

The instructor pilot said that his student had completed four dual circuits with very satisfactory landings off each approach. During the fifth approach, the student flared the aircraft too high and before the instructor could take control, it stalled and struck the ground in a heavy landing.

The left main gear collapsed and the aircraft came to rest on its bent nose gear and left wing tip.

Analysis.

The instructor was unprepared for the high roundout following the student's good landing performance on the previous occasions. He did not take control in time to prevent a heavy landing.