Aviation Safety Investigation Report 199502374

Cessna Aircraft Company Skyhawk

30 July 1995

Aviation Safety Investigation Report 199502374

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199502374 Occurrence Type: Accident

Location: Archerfield, Aerodrome

State: QLD Inv Category: 4

Date: Sunday 30 July 1995

Time: 0927 hours **Time Zone** EST

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172N

Aircraft Registration: VH-TKJ Serial Number: 17270779

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Substantial **Departure Point:** Archerfield Qld

Departure Time:

Destination: Archerfield Qld

Crew Details:

	Hours on		
Role	Class of Licence	Type Hou	rs Total
Pilot-In-Command	Private	400.0	530

Approved for Release: Tuesday, March 12, 1996

The pilot reported that he had completed two touch-and-go landings on runway 22 left and had been cleared for a touch-and-go on runway 22 right which had a displaced threshold. The approach, which was being flown with 20 degrees flap and about 1500 rpm engine power, was shallower than the earlier approaches. The pilot said that, about two metres above the ground, as he was about to increase power slightly to ensure that the aircraft did not touch down before the displaced threshold, the nose dropped. The nosewheel struck the ground firmly and the aircraft nosed over. The pilot could not recall hearing the stall warning sound during the approach, although it had tested serviceable before the flight.