Aviation Safety Investigation Report 199503328

Beech Aircraft Corp Bonanza

07 October 1995

Aviation Safety Investigation Report 199503328

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199503328

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199503328 Occurrence Type: Accident

Location: Maryborough, Aerodrome

State: QLD Inv Category: 4

Date: Saturday 07 October 1995

Time: 1615 hours **Time Zone** EST

Highest Injury Level: None

Aircraft Manufacturer: Beech Aircraft Corp

Aircraft Model: A36

Aircraft Registration: VH-MTM Serial Number: E-471

Type of Operation: Non-commercial Business

Damage to Aircraft:SubstantialDeparture Point:Monto QLDDeparture Time:1530 EST

Destination: Maryborough QLD

Crew Details:

Role Class of Licence Type Hours Total
Pilot-In-Command Private 94.0 220

Approved for Release: Tuesday, March 12, 1996

During the landing roll, at about 60 kts, the pilot inadvertently selected the gear up when he intended to raise the flaps.

The nose and left maingear collapsed. The aircraft came to rest on the runway near a taxiway.