

**Aviation Safety Investigation Report
199503667**

**Cessna Aircraft Company
Skywagon**

02 November 1995

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199503667 **Occurrence Type:** Accident
Location: Kingaroy, Aerodrome
State: QLD **Inv Category:** 4
Date: Thursday 02 November 1995
Time: 1130 hours **Time Zone** EST
Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company
Aircraft Model: A185F
Aircraft Registration: VH-WLW **Serial Number:** 18502884
Type of Operation: Instructional Dual
Damage to Aircraft: Substantial
Departure Point: Kingaroy QLD
Departure Time:
Destination: Kingaroy QLD

Crew Details:

Role	Class of Licence	Hours on Type	Hours Total
Pilot-In-Command		3000.0	20000

Approved for Release: Tuesday, March 12, 1996

The pilot reported that the aircraft was landed downwind during agricultural rating pilot training. After a normal landing, as the aircraft slowed it suddenly swung left. The right wing and propeller struck the ground and the right landing gear was torn off. The wind was gusting from the left rear quarter.