Aviation Safety Investigation Report 199400093

Cessna Aircraft Company Huskey

13 January 1994

Aviation Safety Investigation Report 199400093

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199400093 Occurrence Type: Accident

Location: 3km N Theodore

State: QLD Inv Category: 4

Date: Thursday 13 January 1994

Time: 1135 hours Time Zone EST

Highest Injury Level: Minor

Injuries:

	Fatal	Serious	Minor	None	Total
Crew	0	0	1	0	1
Ground	0	0	0	0	0
Passenger	0	0	0	0	0
Total	0	0	1	0	1

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: T188C

Aircraft Registration: VH-UJN Serial Number: T18803390T

Type of Operation: Commercial Aerial Agriculture - Other

Damage to Aircraft: Destroyed

Departure Point: Theodore QLD

Departure Time:

Destination: Theodore QLD

Crew Details:

	Hours on		
Role	Class of Licence	Type Ho	urs Total
Pilot-In-Command	Commercial	11000.0	16000

Approved for Release: Monday, April 29, 1996

The pilot was spraying a cotton crop in light wind conditions. On the second clean-up run, although aware of the location of a powerline, the pilot could not see the wires due to spray drift contamination of the windscreen. He misjudged the pull up point, and the aircraft struck the wires with the right main landing gear.

The aircraft was retarded by the wires and crashed inverted. The pilot was able to extricate himself before the aircraft was destroyed by fire.