Aviation Safety Investigation Report 199400360

Robinson Helicopter Co R22

12 February 1994

Aviation Safety Investigation Report 199400360

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199400360 Occurrence Type: Accident

Location: 5km W Giru

State: QLD Inv Category: 4

Date: Saturday 12 February 1994

Time: 0949 hours **Time Zone** EST

Highest Injury Level: Minor

Injuries:

	Fatal	Serious	Minor	None	Total
Crew	0	0	1	0	1
Ground	0	0	0	0	0
Passenger	0	0	0	0	0
Total	0	0	1	0	1

Aircraft Manufacturer: Robinson Helicopter Co

Aircraft Model: R22 BETA

Aircraft Registration: VH-THP Serial Number: 0972

Type of Operation: Commercial Aerial Agriculture - Other

Damage to Aircraft:DestroyedDeparture Point:Giru QLDDeparture Time:0937 EST

Destination: Poletto Farm QLD

Crew Details:

	Hours on				
Role	Class of Licence	Type Ho	urs Total		
Pilot-In-Command	Commercial	1500.0	9300		

Approved for Release: Friday, September 16, 1994

The pilot was flying the helicopter in a spraying operation over a paddock adjacent to a farm house. A study of his map and an aerial inspection had led him to believe that a major spur powerline terminated at a transformer near the farm house. However, this was not the case as the three phase powerline continued on in long spans.

He had almost finished the task and required one final spray run at 90 degrees to his previous swaths and the unseen powerline bordering the paddock. As he pulled up after the run, the spray boom collected the wires. The helicopter gyrated, losing the tail boom to a main rotor strike, and crashed some 15 metres beyond the powerline.

The pilot had not seen the powerline at any stage.