

**Aviation Safety Investigation Report
199400486**

**Skyfox Aviation Ltd
Skyfox**

26 February 1994

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199400486 **Occurrence Type:** Accident
Location: Parafield
State: SA **Inv Category:** 4
Date: Saturday 26 February 1994
Time: 1425 hours **Time Zone** CSuT
Highest Injury Level: Minor
Injuries:

	Fatal	Serious	Minor	None	Total
Crew	0	0	1	0	1
Ground	0	0	0	0	0
Passenger	0	0	0	0	0
Total	0	0	1	0	1

Aircraft Manufacturer: Skyfox Aviation Ltd
Aircraft Model: CA25
Aircraft Registration: VH-PFF **Serial Number:** CA22022
Type of Operation: Instructional Solo
Damage to Aircraft: Substantial
Departure Point: Parafield SA
Departure Time: 1345 CSuT
Destination: Parafield SA

Crew Details:

Role	Class of Licence	Hours on	
		Type	Hours Total
Pilot-In-Command	Student	32.0	32

Approved for Release: Sunday, June 19, 1994

The student pilot, returning from a solo training session, carried out a normal circuit and approach for landing, but the aircraft bounced slightly on touchdown. The pilot applied some forward elevator control but the aircraft veered about 90 degrees to the left and ran off the runway.

The pilot unsuccessfully attempted to control the swing with right rudder, then applied full power to go-around. She then observed another aircraft taxiing and turned the aircraft left to avoid that aircraft. The left wing struck the ground and the aircraft cartwheeled.
