**Aviation Safety Investigation Report 199400575** 

**Intermountain Manufacturing Co A-9A** 

08 March 1994

## Aviation Safety Investigation Report 199400575

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199400575 Occurrence Type: Accident

**Location:** 10km NW Korumburra

State: VIC Inv Category: 4

**Date:** Tuesday 08 March 1994

**Time:** 1145 hours **Time Zone** EST

Highest Injury Level: Minor

**Injuries:** 

	Fatal	Serious	Minor	None	Total
Crew	0	0	1	0	1
Ground	0	0	0	0	0
Passenger	0	0	0	0	0
Total	0	0	1	0	1

Aircraft Manufacturer: Intermountain Manufacturing Co

Aircraft Model: A-9A

Aircraft Registration: VH-MPN Serial Number: 1127

**Type of Operation:** Commercial Aerial Agriculture/Baiting

**Damage to Aircraft:** Destroyed

**Departure Point:** Korumburra VIC

**Departure Time:** 1141 EST

**Destination:** Korumburra VIC

**Crew Details:** 

	Hours on				
Role	Class of Licence	Type Hour	's Total		
Pilot-In-Command	Commercial	6.0	308		

**Approved for Release:** Tuesday, June 28, 1994

The pilot had been spreading superphosphate in a paddock to the north of the strip. To get to the paddock the aircraft had to climb over hills. This was achieved with the assistance of updraughts off the hills. On the accident flight the pilot found the updraughts were not present and the aircraft was not climbing adequately. Concerned that he would not be able to clear trees ahead the pilot dumped the load and attempted to turn left. The aircraft struck a tree and spun to the ground. The pilot escaped from the wreckage but the aircraft caught fire and was destroyed.