Aviation Safety Investigation Report 199400756

Cessna Aircraft Company Skyhawk

26 March 1994

Aviation Safety Investigation Report 199400756

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199400756

Occurrence Number: 199400756 Occurrence Type: Accident

Location: Tumut

NSW State: **Inv Category:**

Saturday 26 March 1994 Date:

Time: 1500 hours **Time Zone EST**

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172N

Aircraft Registration: VH-TMS Serial Number: 17269599

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Substantial **Departure Point: Tumut NSW Departure Time:** 1445 EST **Destination: Tumut NSW**

Crew Details:

Hours on

Role	Class of Licence	Type Hou	ırs Total
Pilot-In-Command	Commercial	138.0	304

Approved for Release: Sunday, June 19, 1994

The pilot made an approach to land on runway 35. He reported that conditions in the circuit were turbulent with about eight knots of crosswind on runway 35. Prior to the flare the aircraft entered a high rate of sink. Full power was applied but the pilot was unable to prevent the aircraft from landing heavily. The nosegear collapsed and the propeller hit the runway. The aircraft skidded for a further 80 metres, coming to rest on the grass to the right of the runway.