Aviation Safety Investigation Report 199401317

Mooney Aircraft Corp Mooney

19 May 1994

Aviation Safety Investigation Report 199401317

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199401317 Occurrence Type: Accident

Location: Mount Augustus

State: WA Inv Category: 4

Date: Thursday 19 May 1994

Time: 1330 hours **Time Zone** WST

Highest Injury Level: None

Aircraft Manufacturer: Mooney Aircraft Corp

Aircraft Model: M20J

Aircraft Registration: VH-ECH Serial Number: 24-0869

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Substantial

Departure Point: Meekatharra WA

Departure Time: 1130 WST

Destination: Mt Augustus Station WA

Crew Details:

	Hours on		
Role	Class of Licence	Type Hou	rs Total
Pilot-In-Command	Private	60.0	210

Approved for Release: Wednesday, August 24, 1994

The pilot elected to go around when the aircraft bounced following a fast approach. During the go around sequence, the left wing and the propeller touched the ground and the engine stopped. The pilot was able to recover and land next to the runway.