

**Aviation Safety Investigation Report  
199401788**

**Beech Aircraft Corp  
Baron**

**09 July 1994**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199401788      **Occurrence Type:** Accident  
**Location:** Brisbane QLD  
**State:** QLD      **Inv Category:** 4  
**Date:** Saturday 09 July 1994  
**Time:** 1747 hours      **Time Zone:** EST  
**Highest Injury Level:** None

**Aircraft Manufacturer:** Beech Aircraft Corp  
**Aircraft Model:** 58  
**Aircraft Registration:** VH-SXS      **Serial Number:** TH181  
**Type of Operation:** Non-commercial Pleasure/Travel  
**Damage to Aircraft:** Substantial  
**Departure Point:** Maryborough QLD  
**Departure Time:** 1717 EST  
**Destination:** Bundaberg QLD

**Approved for Release:** Wednesday, November 1, 1995

When the landing gear was selected down for landing at Bundaberg, the landing gear motor was heard to operate only momentarily before the landing gear circuit breaker popped, and a burning smell entered the cabin. The circuit breaker was reset and again the landing gear motor appeared to function only momentarily before the circuit breaker tripped. The pilot advised that he then tried unsuccessfully to lower the landing gear using the manual emergency extension. A decision was then taken to return to Brisbane where a "gear up" landing was carried out. All five occupants were able to exit the aircraft safely.

