**Aviation Safety Investigation Report 199401851** 

**Cessna Aircraft Company Centurion** 

27 June 1994

## Aviation Safety Investigation Report 199401851

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199401851 Occurrence Type: Accident

**Location:** Bathurst Island

State: NT Inv Category: 4

**Date:** Monday 27 June 1994

**Time:** 0915 hours **Time Zone** CST

**Highest Injury Level:** Minor

**Injuries:** 

	Fatal	Serious	Minor	None	Total
Crew	0	0	1	0	1
Ground	0	0	0	0	0
Passenger	0	0	0	0	0
Total	0	0	1	0	1

Aircraft Manufacturer: Cessna Aircraft Company

**Aircraft Model:** 210K

Aircraft Registration: VH-CAZ Serial Number: 21059448

**Type of Operation:** Charter Passenger

**Damage to Aircraft:** Substantial

**Departure Point:** Bathurst Island NT

**Departure Time:** 

**Destination:** Darwin NT

**Approved for Release:** Friday, August 26, 1994

The pilot attempted to start the engine for the return flight to Darwin, but the starter motor failed to operate. He then applied the handbrake, chocked the nose-wheel and hand-swung the propeller. After several attempts the engine fired then ran at a high RPM speed causing the aircraft to jump over the chock and head towards the airport fence.

After unsuccessfully attempting to enter the cabin the pilot tried to grab a main wheel, but missed. He next grabbed at the tailplane but was knocked to the ground. The empty aircraft then ran through the airport fence, across a road and into a ditch, where it came to rest suffering substantial damaged.