Aviation Safety Investigation Report 199403682

Cessna Aircraft Company 182F

27 November 1994

Aviation Safety Investigation Report 199403682

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199403682 Occurrence Type: Accident

Location: Avoid Island

State: QLD **Inv Category:**

Date: Sunday 27 November 1994

Time: 1030 hours Time Zone **EST**

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 182F

Aircraft Registration: VH-CDN Serial Number: 18254906

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Substantial **Departure Point:** Mackay QLD **Departure Time:** 1000 EST

Destination: Avoid Island QLD

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours Total	
Pilot-In-Command	Private	50.0	200

Approved for Release: Friday, March 8, 1996

The pilot stated that he noticed a large piece of timber on the runway in line with the nosewheel during the landing flare. Power was applied and the nose wheel was raised to avoid the timber. During the subsequent landing the nosewheel struck the runway prior to the mainwheels. After returning to Mackay, the aircraft was inspected by an engineer who discovered damage to the firewall.