Aviation Safety Investigation Report 199202553

Cessna Aircraft Company U206G

24 January 1992

Aviation Safety Investigation Report 199202553

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199202553 Occurrence Type: Accident

Location: Lindeman Is

State: QLD Inv Category: 4

Date: Friday 24 January 1992

Time: 1530 hours Time Zone EST

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: U206G

Aircraft Registration: VH-WKH Serial Number:

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Substantial

Departure Point: Lindeman Is QLD

Departure Time:

Destination: Hamilton Is QLD

Approved for Release: Wednesday, June 12, 1996

The aircraft was to take off from Lindeman Island. The strip was reported as being a bit rough. The pilot held the control column full back during the take-off run, however the nose gear struck the ground three or four times. As the aircraft speed approached take-off speed the nose gear collapsed and the aircraft skidded to a halt in a nose-down attitude.