Aviation Safety Investigation Report 199300057

Pitts Aviation Enterprises S-2A

21 January 1993

Aviation Safety Investigation Report 199300057

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199300057

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was

Occurrence Number: 199300057 Occurrence Type: Accident

Location: Newcastle Waters Station

obtained from information supplied to the Bureau.

State: NT Inv Category: 4

Date: Thursday 21 January 1993

Time: 1340 hours Time Zone CST

Highest Injury Level: None

Aircraft Manufacturer: Pitts Aviation Enterprises

Aircraft Model: S-2A

Aircraft Registration: VH-KIT Serial Number: 2032

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft:SubstantialDeparture Point:Tindal NTDeparture Time:1200 CST

Destination: Newcastle Waters NT

Crew Details:

Role Class of Licence Type Hours Total
Pilot-In-Command Private 500.0 3000

Approved for Release: Tuesday, August 9, 1994

The aircraft was landed heavily resulting in the separation of the right hand brake caliper. The pilot lost directional control of the aircraft and it veered off the runway and groundlooped, causing damage to the ailerons, wingtips and the interplane struts.