Aviation Safety Investigation Report 199300392

Piper Aircraft Corp Warrior

06 March 1993

Aviation Safety Investigation Report 199300392

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199300392 Occurrence Type: Accident

Location: Portland

State: VIC Inv Category:

Date: Saturday 06 March 1993

Time: 1245 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Piper Aircraft Corp

Aircraft Model: PA-28-151

Aircraft Registration: VH-HWN Serial Number: 28-7715113

Type of Operation: Instructional Solo

Damage to Aircraft:SubstantialDeparture Point:Portland VICDeparture Time:1215 ESuTDestination:Portland VIC

Crew Details:

	Hours on		
Role	Class of Licence	Type Hours	s Total
Pilot-In-Command	Student	25.0	35

Approved for Release: Thursday, July 22, 1993

During a touch and go landing, the student pilot lost directional control and the aircraft veered off the runway to the right. The aircraft hit part of the TVASIS installation.