Aviation Safety Investigation Report 199300407

Cessna Aircraft Company Cessna Skyhawk Cessna Aircraft Company Skyhawk

18 February 1993

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number:	199300/07	Occurrence Type	• Incident
Location:		Occurrence Type	• Inclucint
	Moorabbin Airport	TOA	4
State:	VIC	Inv Category:	4
Date:	Thursday 18 February 199		
Time:	1306 hours	Time Zone	ESuT
Highest Injury Level: None			
Aircraft Manufacturer: Cessna Aircraft Company			
Aircraft Model:	172M	.9	
Aircraft Registration:		Sorial Nr	mber: 17262988
Type of Operation:	Non-commercial Pleasure/Travel		
•• •	Nil		
Damage to Aircraft:	1811		
Departure Point:			
Departure Time:			
Destination:	Moorabbin VIC		
Aircraft Manufacture	er: Cessna Aircraft Compan	y	
Aircraft Model:	172P	-	
Aircraft Registration:	VH-JRB	Serial Number:	17274516
Type of Operation:	Instructional Unknown		
Damage to Aircraft:	Nil		
Departure Point:			
Departure Time:			
Destination:			

Approved for Release: Thursday, June 10, 1993

VH-JRB approached the airport from the south and on right downwind for runway 17R was told he was number one in the sequence. VH-IRH came in via Point Ormond to the north, also for runway 17R, the pilot being told to report at Southland.

When he called at Southland the pilot of VH-IRH recived an acknowledgement but no instructions or traffic information. The two aircraft came into close proximity at about the base leg position. Both pilots saw each other in just enough time to deviate and miss.

In nominating Southland as a reporting point for VH-IRH the controller selected a point close to the base position. He was initially unable to see VH-IRH when he called at Southland. As this was close to base leg position a conflict occurred before any further action was taken by him. Timely traffic information was not passed to both aircraft.