Aviation Safety Investigation Report 199300682

Bell Helicopter Co Sioux

28 March 1993

Aviation Safety Investigation Report 199300682

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199300682

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199300682 Occurrence Type: Accident

Location: Scartwater Station, via Collinsville

State: QLD **Inv Category:**

Date: Sunday 28 March 1993

Time: 1800 hours Time Zone **EST**

Highest Injury Level: None

Aircraft Manufacturer: Bell Helicopter Co

Aircraft Model: 47G-4

Aircraft Registration: VH-NXB Serial Number: 3146

Type of Operation: Non-commercial Business

Damage to Aircraft: Destroyed

Departure Point: Departure Time:

Destination: Scartwater Station QLD

Approved for Release: Wednesday, July 28, 1993

The pilot reported that the helicopter's engine lost power during normal cruise flight. A forced landing was conducted into small trees resulting in the helicopter catching fire and being destroyed. Later inspection of the wreckage by an aircraft engineer revealed a hole in the crankcase caused by a connecting rod which had separated from the crankshaft.