

**Aviation Safety Investigation Report  
199301022**

**Cessna Aircraft Company  
Skywagon**

**22 April 1993**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199301022                      **Occurrence Type:** Accident  
**Location:** Ballarat  
**State:** VIC    **Inv Category:** 4  
**Date:** Thursday 22 April 1993  
**Time:** 1430 hours                                      **Time Zone** EST  
**Highest Injury Level:** None

**Aircraft Manufacturer:** Cessna Aircraft Company  
**Aircraft Model:** A185F  
**Aircraft Registration:** VH-UJH                      **Serial Number:** 18503679  
**Type of Operation:** Instructional Solo  
**Damage to Aircraft:** Substantial  
**Departure Point:** Ballarat VIC  
**Departure Time:** 1340 EST  
**Destination:** Ballarat VIC

**Crew Details:**

<b>Role</b>	<b>Class of Licence</b>	<b>Hours on Type</b>	<b>Hours Total</b>
Pilot-In-Command	Commercial	26.0	196

**Approved for Release:** Monday, April 26, 1993

After a session in the training area the pilot returned for landing on runway 36. Following an apparently normal touchdown the aircraft slowed, but then the left wing lifted. A correction was made for this but the aircraft swung left and the right main landing gear leg collapsed.

---