Australian Government Australian Transport Safety Bureau Australian Transport Safety Bureau Aviation Notification Form							
Notification Officer: S. 47F(1)			Phone: 1800 011 034				
All orange fields are Mandatory unless information is not available from Reporter							
Reporters Name:	s. 47F(1)		Role:	Member	of public	Employer	
Report date:	30/12/2016	R	eport time:	1930		Phone:	s. 47F(1)
Registration:	193050	Flight No:		Airc	craft Type:		abiru? 7, Cessna 210
Occurrence type:	eg. Loss of separat	ion, wheels up la	anding	Opera	tion Type:		k, mustering, private
Occurrence Date:				ence Time:		O Local	Оитс
Occurrence location:	Krollig Rd Loxto	on				State:	SA
Latitude/Longitude:	Important for accide	ents away from a	aerodromes]	
Aircraft Operator:	mportant for addition						
Injuries	Fatal	Serious	Minor	Nil			
Crew							
Passengers Ground							
Damage description:					l		
zamago accompación							
Description of occurr	ence and Addi	tional Inform	nation: (Press	ALT + ENTER	for a new para	agraph)	
Aircraft accident site se						nd the aircra	oft with note
taped to side stating no	one was injure	d and to call	s. 4/F(1)	for further d	etails.		
FIt Recs Quarantined: O Yes O No ELT Disabled O Yes O No Guard: O Yes O No							
Passed on: Date	Time	Name			Date	Time	Name
COR: #######	2030	s. 47F(1)		WebSMS:			
Other:				Other:			

201605448 - Occurrence Summary

Overview	
Occurrence date	30 Dec 16
Occurrence time	19:30 CSuT
Logged date	11 Jan 17
Occurrence category	Accident
ATSB involvement	Data entry
Status	Reviewed
Highest injury	Minor


Occurrence Types	
Operational - Terrain Collisions - Collision with terrain	П
Operational - Terrain Collisions - Wirestrike	П

	Aircrafts Summary				
	Registration	Model Common Name	Maximum Weight Category	Operation Type	
S.	47F(1)	SK	0-2250 Kg (0-4960 Lbs)	Private	

Safety Factors
Individual action - Aircraft operation action - Other aircraft operation action

Summary	
ATSB summary	The aircraft struck power lines and collided with terrain.

Aviation Accident or Incident Notification



From: <u>Safety</u>

To: <u>ASIRFollowup</u>; <u>ATSBASIR</u>

Cc: s. 4/F(1) <u>ecreational Aviation Australia (RA-Aus) - Operations manager (24 hours);</u>

Subject: Outcome of RAAus Investigation into accident Jabiru 19-3050 dated 30 December 2016 at Moorook SA

Date: Friday, 24 March 2017 2:03:44 PM

image001.png image002.png image003.png image004.png

Dear ATSB,

Attachments:

RAAus wishes to advise you of the outcome of a RAAus investigation into aviation accident (RAAus report OCC0867):

Incident Date: 30 December 2016
Incident Location: Moorook SA
Aircraft: 5: 47F(1) Jabiru SK4

The following accident was reported as follows:

SUMMARY: Initial report stated that the aircraft experienced a rough running engine when coming into land in a field, where the aircraft struck power lines. Aircraft has been destroyed and the pilot and passenger had minor injuries.

RAAus investigations have determined the following outcome:

OUTCOME: RAAus Operations had discussions with PIC regarding possible casual factors which led to this incident. PIC admit that the aircraft did not experience engine difficulties and that they were actually flying low causing the aircraft to strike power lines. Operations has proposed for the PIC to complete a Low Level (LL) training (not for issues of LL endorsement, for educational purposes) with an appropriately endorsed CFI prior to any further flight.

RAAus now deem this report as closed and this email is to advise the ATSB that the classification of this report is different from the original summary (Rough running engine was not a factor however it was due to low level flying). We have also included s. 47F(1) for information purposes.

If you would like to discuss this outcome further please do not hesitate to contact me.

Kind regards,

s. 47F<u>(1)</u>

Safety, Risk and Compliance Manager

RAAus: Creating opportunities

P: (02) 6280 4700
W: www.raa.asn.au





NSO: Disclaimer

This message has been issued by Recreational Aviation Australia. The information transmitted is for the use of the intended recipient only and may contain confidential and/or legally privileged material. Any review, retransmission, disclosure, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited. If you have received this e-mail in error, please notify Recreational Aviation Australia (02) 6280-4700 and delete all copies of this transmission together with any attachments. Please consider the environment before printing this email.

From: ATSB International Reporting

To: "info account"

Subject: ACCID 201605448 19-3050 near Waikerie SA 30 December 2016 [SEC=UNCLASSIFIED]

 Date:
 Wednesday, 11 January 2017 12:57:00 PM

 Attachments:
 State Of Manufacture Notification.pdf

Good afternoon,

Attached is notification of an accident involving a Jabiru SK with Jabiru engine. Please forward to the relevant personnel.

The ATSB is not investigating this accident.

Regards,

s. 47F(1)

International Reporting and Investigation Quality Assurance Australian Transport Safety Bureau

62 Northbourne Avenue Canberra ACT 2601

s. 47F(1)

Australia's national transport safety investigato

AVIATION | MARINE | RAIL

Web www.atsb.gov.au Twitter @ATSBinfo



ICAO Annex 13 Chapter 4 Accident & Serious Incident Notification

ATSB Reference: 201605448 Category: Accident

Investigation: No

Date and Time: Friday, December 30, 2016 7:30 PM CSuT

Location: Waikerie Aerodrome, 118.51° T 34Km

State: SA Country: Australia Latitude: -34.3295 Longitude: 140.3542

Highest Injury: Minor

Occurrence: Operational - Terrain Collisions - Collision with terrain

Site Access: Accessible

Dangerous Goods: Nil

Injury Details:		Crew	Passenger	Ground
	Fatal	0	0	0
	Serious	0	0	0
	Minor	1	1	0
	Nil	0	0	_

Nationalitites: N/A

Aircraft Details:

s. 47F(1)

Aircraft Type: Aeroplane

Serial Number: 111

Manufacturer: Jabiru Aircraft Pty Ltd

Model: SK
Engine Manufacturer: Jabiru
Engine Model: 2200A

Operation: Private Unknown

Damage Level:SubstantialCountry of Registration:AustraliaCountry of Manufacture:Australia

Departed: Kingston on Murray SA

Destination: Moorook SA

Summary: During cruise, the engine began running roughly. While conducting a

precautionary landing, the aircraft struck a power line and was substantially

damaged.