



Occurrences Entered into the ATSB Maritime Safety Database
Between 03 April 2021 and 09 April 2021

Occurrence Date	ATSB Reference Number	Occurrence Time	Time Zone	Investigation	Location	Vessel Name	Identifier Type	Identifier	Occurrence Type	Summary
03/04/2021	MA202100253	9:00	UTC+8	No	Dampier	Bunun Wisdom	IMO No	9628568	Serious injury	While conducting routine maintenance on deck, a crewman fell approximately 5 metres from a mast resulting in serious injuries.
04/04/2021	MA202100259	0:20	UTC+11	No	Bass Strait	Goliath	IMO No	9036430	Machinery failure	During ocean passage, the crew received a high temperature alarm on the no. 4 generator. The generator shut down uncommanded resulting in a full-ship blackout. After switching to the no. 1 generator, the vessel's systems were restored and passage resumed within 10 minutes. The ship's engineers inspected the no. 4 generator and found a cooling jacket leak on the no. 3 cylinder.
05/04/2021	MA202100249	12:00	UTC+8	Yes - MO-2021-003	1700 NM SW Perth	MPV Everest	IMO No	9769130	Fire / explosion	During ocean passage, the crew detected a fire in the port main engine room. The crew activated the fixed fire-fighting system and cooled the engine room perimeter. Once the fire was extinguished, the crew restarted the starboard engine and the vessel resumed passage at reduced speed. The investigation is continuing.
07/04/2021	MA202100260	5:00	UTC+10	No	70 NM E Curtis Island	Adelie	IMO No	9207807	Machinery failure	During ocean passage, the ship's engineer detected a leak from the head gasket of the no. 6 cylinder on the main engine. The engine was shut down and the vessel set to drift while repairs were conducted by the crew.

Note: For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter that the ATSB has decided not to investigate, as identified in this publication, are not to be treated as OBR on and after the date of publication of this weekly summary.

Section 48 of the TSI Act contains a definition of an OBR. The voice component of a Voyage Data Recorder normally meets the requirements of an OBR.

Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBR. When an OBR is declared not to be an OBR other protections may continue to apply such as those relating to personal information under privacy legislation.