

**Aviation Safety Investigation Report
199200493**

**Beech Aircraft Corp
Baron**

04 November 1992

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 199200493 **Occurrence Type:** Incident
Location: Near FITZROY CROSS.6E
State: WA **Inv Category:** 4
Date: Wednesday 04 November 1992
Time: 1530 hours **Time Zone** WSuT
Highest Injury Level: None

Aircraft Manufacturer: Beech Aircraft Corp
Aircraft Model: 58
Aircraft Registration: VH-AYV **Serial Number:** TH-1231
Type of Operation: Air Transport High Capacity Training
Damage to Aircraft: Minor
Departure Point: HALLS CREEK WA
Departure Time:
Destination: FITZROY CROSSING WA

Approved for Release: Tuesday, April 27, 1993

The pilot reported that during the descent into Fitzroy Crossing he diverted to inspect a fishing pool. During the inspection the descent continued unnoticed and the aircraft collided with an object, later identified as a power line. The aircraft continued to operate normally and landed safely at Fitzroy Crossing.