

**Aviation Safety Investigation Report  
199803763**

**Boeing Co  
B747**

**11 September 1998**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**



The operator, in conjunction with the overseas freight handling agent, instigated an immediate retraining program for all staff involved in export handling procedures. In addition, new instructions have been issued for the handling of dangerous goods.

