



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
19/12/08	200808439	Incident	No	Richmond (NSW) Aerodrome, 123° M 19Km	NSW	Unknown	Unknown	Unknown	Unknown	CTR	C	An unidentified aircraft was observed by ATC to have entered controlled airspace without a clearance.
9/01/09	200907679	Incident	No	Richmond (NSW) Aerodrome, 095° M 15Km	NSW	CESSNA AIRCRAFT COMPANY	172S	Unknown	Unknown	CTR	C	The aircraft was assigned 2,500 ft but descended without a clearance.
12/01/09	200907680	Incident	No	Richmond (NSW) Aerodrome, 270° M 31Km	NSW	Unknown	Unknown	Unknown	Unknown	CTR	C	An unidentified aircraft was observed by ATC to have entered controlled airspace without a clearance.
15/01/09	200907592	Incident	No	Pearce Aerodrome, 180° M 83Km	WA	CESSNA AIRCRAFT COMPANY	172N	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R166 without a clearance.
20/01/09	200907682	Incident	No	Oakey Aerodrome, 040° M 43Km	QLD	CESSNA AIRCRAFT COMPANY	182S	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R643A without a clearance.
2/02/09	200907591	Incident	No	Lancelin Township (VFR), 045° M 28Km	WA	CESSNA AIRCRAFT COMPANY	206H	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
2/02/09	200907683	Incident	No	near Colonsay (ALA)	QLD	Unknown	Unknown	Aerial Work	Aerial Agriculture	PRD	PRD	The aircraft conducted agricultural operations in R643B without notifying Oakey ATC.
6/02/09	200907589	Incident	No	Cervantes (ALA), 180° M 15Km	WA	PIPER AIRCRAFT CORP	PA-28R-180	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
6/02/09	200907590	Incident	No	Lancelin Township (VFR), 331° M 20Km	WA	PIPER AIRCRAFT CORP	PA-28-140	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
10/02/09	200907684	Incident	No	near Toowoomba Aerodrome	QLD	PIPER AIRCRAFT CORP	PA-28R-200	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R643A without a clearance.
11/02/09	200907593	Incident	No	Pearce Aerodrome, 313° M 67Km	WA	CESSNA AIRCRAFT COMPANY	182Q	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
17/02/09	200907594	Incident	No	Pearce Aerodrome, 053° M 52Km	WA	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R153D without a clearance.
23/02/09	200907595	Incident	No	Lancelin Township (VFR), N M 19Km	WA	Unknown	Unknown	Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R146A without a clearance.
24/02/09	200907596	Incident	No	Gingin Aerodrome, 247° M 19Km	WA	AEROSPATIALE INDUSTRIES	AS.350B2	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
27/02/09	200907599	Incident	No	Pearce Aerodrome, 195° M 99Km	WA	Unknown	Unknown	Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R166A without a clearance.
27/02/09	200907600	Incident	No	Pearce Aerodrome, 320° M 76Km	WA	CESSNA AIRCRAFT COMPANY	182P	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
16/03/09	200907598	Incident	No	Pearce Aerodrome, 030° M 80Km	WA	AMATEUR BUILT AIRCRAFT	VAN'S RV-9A	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R153D without a clearance.
17/03/09	200907619	Incident	No	Lancelin Township (VFR), 039° M 67Km	WA	CESSNA AIRCRAFT COMPANY	206H	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
19/03/09	200907620	Incident	No	Cervantes (ALA), 090° M 40Km	WA	CESSNA AIRCRAFT COMPANY	182Q	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
31/03/09	200907624	Incident	No	Collie (ALA), 326° M 35Km	WA	Unknown	Unknown	Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R166 without a clearance.
8/04/09	200907625	Incident	No	Pearce Aerodrome, 270° M 28Km	WA	DE HAVILLAND CANADA	DHC-8-202	Aerial Work	Survey / Photographic	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
9/04/09	200907638	Incident	No	Pearce Aerodrome, 198° M 99Km	WA	CESSNA AIRCRAFT COMPANY	T206H	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R166A without a clearance.
20/04/09	200907641	Incident	No	Collie (ALA), 358° M 51Km	WA	Unknown	Unknown	Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R166A without a clearance.
21/04/09	200907642	Incident	No	Jurien Bay (ALA), 328° M 20Km	WA	CESSNA AIRCRAFT COMPANY	210R	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R160A without a clearance.
21/04/09	200907646	Incident	No	Pearce Aerodrome, N M 96Km	WA	CESSNA AIRCRAFT COMPANY	172P	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 and R155 without a clearance.
29/04/09	200907647	Incident	No	Pearce Aerodrome, 350° M 81Km	WA	CESSNA AIRCRAFT COMPANY	172R	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance. The pilot subsequently reported difficulty with navigation.
5/05/09	200907681	Incident	No	Pearce Aerodrome, N M 107Km	WA	CESSNA AIRCRAFT COMPANY	172P	Flying Training	Training Solo	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
5/05/09	200907694	Incident	No	Pearce Aerodrome, 320° M 111Km	WA	PIPER AIRCRAFT CORP	PA-28-161	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
5/05/09	200907695	Incident	No	Pearce Aerodrome, 020° M 93Km	WA	CESSNA AIRCRAFT COMPANY	172P	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
6/05/09	200907696	Incident	No	Lancelin Township (VFR), S M 28Km	WA	GIPPSLAND AERONAUTICS PTY LTD	GA-8	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
11/05/09	200907698	Incident	No	Pearce Aerodrome, 311° M 70Km	WA	CESSNA AIRCRAFT COMPANY	210L	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R160 without a clearance.
12/05/09	200907697	Incident	No	Pearce Aerodrome, 324° M 128Km	WA	PARTENAVIA COSTRUZIONI AERONAUTICHE SPA	P.68B	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
12/05/09	200907700	Incident	No	Bunbury (ALA), NE M 42Km	WA	CESSNA AIRCRAFT COMPANY	172R	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R166 without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
14/05/09	200907597	Incident	No	Toowoomba Aerodrome, 304° M 9Km	QLD	MOONEY AIRCRAFT CORP	M20E	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R655 without a clearance.
14/05/09	200907699	Incident	No	Cervantes (ALA), 150° M 13Km	WA	CESSNA AIRCRAFT COMPANY	182Q	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R156 without a clearance.
15/05/09	200907703	Incident	No	Pearce Aerodrome, N M 80Km	WA	CESSNA AIRCRAFT COMPANY	A185F	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
18/05/09	200907601	Incident	No	Oakey Aerodrome, 281° M 43Km	QLD	JABIRU AIRCRAFT PTY LTD	J170-C	Unknown	Unknown	PRD	PRD	The aircraft was observed on radar to have entered R643C without a clearance.
19/05/09	200907702	Incident	No	Pearce Aerodrome, 300° M 46Km	WA	AMERICAN AIRCRAFT CORP	AA-5B	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R160 without a clearance.
25/05/09	200907701	Incident	No	Pearce Aerodrome, 318° M 39Km	WA	CIRRUS DESIGN CORPORATION	SR22	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
26/05/09	200907704	Incident	No	Pearce Aerodrome, 330° M 35Km	WA	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R155 without a clearance.
27/05/09	200907705	Incident	No	Jandakot Aerodrome, 173° M 109Km	WA	DIAMOND AIRCRAFT INDUSTRIES	DA-20-C1	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R166 without a clearance.
10/06/09	200907604	Incident	No	Oakey Aerodrome, 285° M 43Km	QLD	CESSNA AIRCRAFT COMPANY	182T	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R643C without a clearance.
10/06/09	200907706	Incident	No	Pearce Aerodrome, 340° M 69Km	WA	BELL HELICOPTER CO	206L-3	Aerial Work	Survey / Photographic	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
11/06/09	200907605	Incident	No	Oakey Aerodrome, 131° M 15Km	QLD	AERO COMMANDER	680-FL(P)	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R643A without a clearance.
24/06/09	200907606	Incident	No	Oakey Aerodrome, 152° M 17Km	QLD	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R643A without a clearance.
25/06/09	200907707	Incident	No	Pearce Aerodrome, 310° M 59Km	WA	AMATEUR BUILT AIRCRAFT	VAN'S RV-8A	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R155 without a clearance.
1/11/09	200907685	Incident	No	Hamilton Aerodrome	VIC	FAIRCHILD INDUSTRIES INC	SA227-AC	Air Transport Low Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a bird that impacted the propeller.
4/11/09	200907492	Serious Incident	No	Canberra Aerodrome	ACT	CESSNA AIRCRAFT COMPANY	150M	General Aviation-Unknown	Unknown	CTR	C	During final approach, with low fuel levels, the fuel flow to the engine was interrupted by aircraft movement. The aircraft sustained a total power loss. The pilot conducted a glide approach and landed on runway 35.
11/11/09	200907055	Incident	No	Parafield Aerodrome	SA	Unknown	Unknown	General Aviation-Unknown	Unknown	CTAF (R)	G	The Grob G-115 aircraft landed on runway 21R and was still occupying the runway when an aircraft landed on runway 21R.
						GROB - BURKHAART FLUGZEUGBAU	G-115	Flying Training	Training Dual			

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
23/11/09	200907621	Incident	No	near Dili International Airport	Other	AEROSPATIALE INDUSTRIES	AS.332L	Charter	Passenger	Other	Foreign	During the approach, the landing gear failed to extend. The crew conducted an emergency landing gear extension and landed. The subsequent maintenance inspection revealed no fault.
23/11/09	200907739	Incident	No	near Cape Flattery (ALA)	QLD	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTA	E	The Reef Sector controller did not coordinate the aircraft's change of level to the Tops Sector controller.
24/11/09	200907634	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the push back, the aircraft's standby electric power failed.
25/11/09	200907708	Incident	No	near Ngujima-yin	WA	AEROSPATIALE INDUSTRIES	AS.332L	Charter	Passenger	OCTA	G	On approach, the master caution and transmission chip light illuminated. The plug had a small amount of carbon, but no metal detected. During the subsequent engineering inspection, the circuit board for the auxiliary warning system was replaced.
26/11/09	200907331	Incident	No	near Sydney Aerodrome	NSW	The Boeing Company	777-312/ER	Air Transport High Capacity	Passenger	CTA	A	Brisbane ATC coordinated the aircraft to the Wollongong sector controller instead of the Katoomba sector controller who had jurisdiction of the aircraft's FDR. At some time after coordination, the Katoomba controller incorrectly inhibited the aircraft's FDR.
27/11/09	200907868	Incident	No	EXROM (IFR)	TAS	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	A	At top of descent, an unrestrained service cart struck the foot of a passenger, causing a minor injury.
28/11/09	200907686	Incident	No	Goolwa (ALA)	SA	CIRRUS DESIGN CORPORATION	SR20	Flying Training	Training Dual	CTAF	G	During the landing, the aircraft's tail scraped the runway surface, resulting in minor damage.
30/11/09	200907522	Incident	No	Temora Aerodrome	NSW	AMATEUR BUILT AIRCRAFT	T-18	General Aviation-Unknown	Unknown	CTAF	G	The pilot reported losing directional control of the aircraft during the take-off run. The pilot suspects a brake may have locked up.
30/11/09	200907895	Incident	No	MEPAB (IFR)	Other	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	OCA	A	While the seat belt sign was illuminated due to turbulence, two passengers left their seats and refused to return when requested by cabin crew.
1/12/09	200907532	Incident	No	Cairns Aerodrome, 300° M 24Km	QLD	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTA	C	While conducting a BIBOORA ONE ALPHA STAR, the crew did not comply with the tracking requirements as specified in the published procedures.
1/12/09	200907546	Incident	No	Darwin Aerodrome	NT	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	During the take-off run, the aircraft struck a curlew.
1/12/09	200907552	Incident	No	Sydney Aerodrome, 338° M 80Km	NSW	Lockheed	C130	Military	Other	CTA	C	The enroute controller failed to coordinate a change in level to the approach controller.
1/12/09	200907553	Incident	No	Scone Aerodrome, 132° M 41Km	NSW	RAYTHEON AIRCRAFT COMPANY	B200	Aerial Work	EMS	CTA	A	During the cruise, the pilot became medically incapacitated with severe stomach cramps.
1/12/09	200907818	Incident	No	Brisbane Aerodrome, SE M 56Km	QLD	JETSTREAM AIRCRAFT LTD	4101	Air Transport Low Capacity	Passenger	CTA	C	The aircraft was observed by ATC to have climbed above the assigned altitude without a clearance.
2/12/09	200907583	Incident	No	near Bathurst Island Aerodrome	NT	CESSNA AIRCRAFT COMPANY	310R	General Aviation-Unknown	Unknown	OCTA	G	During cruise, the radio failed. The aircraft diverted to Bathurst Island.
2/12/09	200907584	Incident	No	abeam Coffs Harbour Aerodrome	NSW	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 170-100 LR	Air Transport High Capacity	Passenger	CTA	A	During cruise, the crew received an indication of a vibration in the left engine. The aircraft diverted to Brisbane. During the subsequent maintenance inspection a fan trim balance was conducted.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
2/12/09	200907585	Incident	No	Mount Isa Aerodrome	QLD							The VHF frequency failed in the Mount ISA area.
2/12/09	200907586	Incident	No	Hobart Aerodrome	TAS	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	D	During the take-off run, the aircraft struck a bird.
2/12/09	200907587	Incident	No	WARTY (IFR)	NSW	Airbus Industries	A330-202	Air Transport High Capacity	Passenger	CTA	C	The crew did not comply with the instruction to track overhead waypoint WARTI. The aircraft turned prior to the waypoint and entered R595 without a clearance.
2/12/09	200907602	Incident	No	Avalon Aerodrome	VIC	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	During the landing roll on runway 18, the aircraft struck a sparrow.
2/12/09	200907603	Incident	No	Amberley Aerodrome, 335° M 59Km	QLD	THE BOEING COMPANY	KC-135	Military	Other	CTA	C	During the cruise when the aircraft diverted to the left of track, Amberley approach did not coordinate the aircraft's details to Brisbane ATC before the aircraft entered Brisbane controlled airspace.
2/12/09	200907607	Incident	No	Albert Park Lake (VFR)	VIC	PIPER AIRCRAFT CORP	PA-22-135	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
2/12/09	200907608	Incident	No	Archerfield Aerodrome, 219° M 31Km	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	A	During cruise, the crew noticed fumes in the cockpit. No fault could be found during the subsequent engineering inspection.
2/12/09	200907609	Incident	No	Darwin Aerodrome, 105° M 96Km	NT	BEECH AIRCRAFT CORP	1900D	Air Transport Low Capacity	Passenger	OCTA	G	During the cruise, the aircraft was struck by lightning.
2/12/09	200907611	Incident	No	Moorabbin Aerodrome	VIC	HEDARO INTERNATIONAL P/L, T/A SKYFOX AVIATION	CA25N	General Aviation-Unknown	Unknown	GAAP	GAAP	The Cessna 172 had been cleared to land but was sent around at 100 ft when the Skyfox CA25N entered the runway without a clearance.
						CESSNA AIRCRAFT COMPANY	172R	General Aviation-Unknown	Unknown			
2/12/09	200907612	Incident	No	near Sydney Aerodrome	NSW	AIRBUS INDUSTRIE	A330-203	Air Transport High Capacity	Passenger	CTA	C	During the approach, fumes were noticed in the forward galley and in the cockpit. No fault could be found with the aircraft.
2/12/09	200907613	Incident	No	Sydney Aerodrome	NSW	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTR	C	During taxi, the aircraft struck a starling that impacted the left propeller.
2/12/09	200907614	Incident	No	Wagga Wagga Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTAF (R)	G	The safety officer retrieved a magpie carcass from the taxiway.
2/12/09	200907628	Incident	No	near Los Angeles International Airport	Other	AIRBUS INDUSTRIE	A380-842	Air Transport High Capacity	Passenger	Other	Foreign	During the approach, the ILS failed to capture the localizer.
2/12/09	200907631	Incident	No	Darwin Aerodrome	NT	THE BOEING COMPANY	717-200	Air Transport High Capacity	Passenger	CTR	C	During the final approach, the aircraft struck a bird that impacted the left side of the fuselage.
2/12/09	200907632	Incident	No	Ballina/Byron Gateway Aerodrome	NSW	Unknown	Unknown	Private	Unknown	CTAF (R)	G	It was reported that the aircraft was operating in the CTAF (R) with the incorrect frequency selected.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
2/12/09	200907636	Incident	No	Noonkanbah (ALA), 250° T 16Km (Kalyeeda Homestead)	WA	CESSNA AIRCRAFT COMPANY	208B	Unknown	Unknown	OCTA	G	During the landing roll, the aircraft struck a bird that impacted the radome.
2/12/09	200907648	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a bird that impacted the nosewheel.
2/12/09	200907662	Incident	No	near Alice Springs Aerodrome	NT	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	CTA	A	The crew received a conditional clearance to climb to FL 380, but commenced climb six minutes early.
3/12/09	200907610	Incident	No	near Brisbane Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	C	The crew did not comply with the SID tracking requirements as specified in the published procedures.
3/12/09	200907615	Incident	No	Cairns Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	441	General Aviation-Unknown	Unknown	CTR	C	While in receipt of an airways clearance, the aircraft taxied to runway 15 holding point without a clearance.
3/12/09	200907616	Incident	No	Perth Aerodrome	WA	THE BOEING COMPANY	717-200	Air Transport High Capacity	Passenger	CTR	C	While the Boeing 767 was being loaded at the gate, a cargo container was blown off the cart by jet blast from the taxiing Boeing 717.
						THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger			
3/12/09	200907617	Incident	No	Gold Coast Aerodrome, 130° M 13Km	NSW	FAIRCHILD INDUSTRIES INC	SA227-AC	Charter	Freight	CTR	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
3/12/09	200907618	Incident	No	Mullumbimby (VFR)	NSW	CESSNA AIRCRAFT COMPANY	172RG	Flying Training	Training Dual	OCTA	G	While inbound, the aircraft encountered turbulence and the pilot heard a loud noise emanating from the fuselage. An inspection revealed that the noise was the flapping of a safety vest through the rear of the passenger door against the airframe. Further inspection revealed that part of the passenger door seal had detached from the door.
3/12/09	200907622	Incident	No	Bankstown Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	172N	General Aviation-Unknown	Unknown	GAAP	GAAP	On downwind, the aircraft was observed by ATC to descend below the published GAAP arrival altitude without a clearance.
3/12/09	200907627	Incident	No	Bankstown Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	172N	Flying Training	Training Solo	GAAP	GAAP	While taxiing after landing, the aircraft's wing tip struck the tail of an aircraft parked on the flight line.
3/12/09	200907629	Incident	No	Sydney Aerodrome, 278° M 31Km	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	CTA	C	The unidentified balloon was observed by the pilot of a departing aircraft to have entered controlled airspace without a clearance.
3/12/09	200907630	Incident	No	Rockhampton Aerodrome	QLD	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTR	D	During the take-off run, the aircraft struck a bird that impacted the left engine. The takeoff was rejected.
3/12/09	200907635	Incident	No	Sydney Aerodrome, 350° M 59Km	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	CTA	C	An unidentified aircraft was observed by ATC to have entered controlled airspace without a clearance.
3/12/09	200907637	Incident	No	Bankstown Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	A152	General Aviation-Unknown	Unknown	GAAP	GAAP	The Grob 115 entered the circuit at the incorrect level, resulting in the aircraft passing in close proximity to a Cessna 152 on crosswind for another runway. The aircraft passed within 100 ft vertically and 100 metres horizontally.
						GROB - BURKHAART FLUGZEUGBAU	G-115	General Aviation-Unknown	Unknown			

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
3/12/09	200907639	Incident	No	IDOTO (IFR)	Other	BEECH AIRCRAFT CORP	B300	General Aviation-Unknown	Unknown	OCA	A	The coordination details were passed late by the Brisbane controller to the Ujung Pandang controller. The details had been provided to the incorrect area.
3/12/09	200907645	Incident	No	Parafield Aerodrome	SA	PIPER AIRCRAFT CORP	PA-31-350	General Aviation-Unknown	Unknown	GAAP	GAAP	The aircraft was cleared to cross the undershoot of runway 26R but was subsequently observed to have entered runway 26R without a clearance.
3/12/09	200907649	Incident	No	Archerfield Aerodrome, NW M 2Km	QLD	MCDONNELL DOUGLAS HELICOPTER COMPANY	369D	General Aviation-Unknown	Unknown	GAAP	GAAP	The helicopter became airborne within controlled airspace without a clearance. ATC was unable to establish communication with the pilot.
3/12/09	200907650	Incident	No	Adelaide Aerodrome, 342° M 78Km	SA	CESSNA AIRCRAFT COMPANY	A152	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R253 without a clearance.
3/12/09	200907651	Incident	No	Eildon Weir VOR, SW M 24Km	VIC	CESSNA AIRCRAFT COMPANY	T210M	General Aviation-Unknown	Unknown	CTA	C	An unidentified aircraft was observed by ATC to have entered controlled airspace without a clearance.
3/12/09	200907652	Incident	No	near Bathurst Aerodrome	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R520 without a clearance.
3/12/09	200907653	Incident	No	Perth Aerodrome, E M 28Km	WA	ROBINSON HELICOPTER CO	R22 BETA	General Aviation-Unknown	Unknown	CTA	C	The helicopter was observed by ATC to have entered controlled airspace without a clearance.
3/12/09	200907656	Incident	No	Perth Aerodrome, 072° M 59Km	WA	CESSNA AIRCRAFT COMPANY	172P	General Aviation-Unknown	Unknown	OCTA	G	While the aircraft was inbound, the radio receiver failed.
3/12/09	200907658	Incident	No	NUMSA (IFR)	Other	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the crew did not update a waypoint estimate and the aircraft passed waypoint NUMSA ten minutes early.
3/12/09	200907663	Incident	No	Horn Island Aerodrome	QLD	REIMS AVIATION S.A.	F406	Air Transport Low Capacity	Passenger	CTAF (R)	G	During the landing, the aircraft struck a bird that impacted the right wing.
3/12/09	200907669	Accident	No	Oakey Aerodrome, 046° M 43Km	QLD	YAKOVLEV AIRCRAFT FACTORIES	YAK-18T	Private	Unknown	OCTA	G	During cruise, the engine failed. The pilot conducted a forced landing into a paddock where the aircraft struck a fence, resulting in serious damage to the aircraft.
3/12/09	200907674	Incident	No	Outer Harbor (VFR), W M 15Km	SA	CESSNA AIRCRAFT COMPANY	172N	Flying Training	Unknown	OCTA	G	During cruise, the alternator failed intermittently.
3/12/09	200907675	Incident	No	Gove Aerodrome, W M 37Km	NT	CESSNA AIRCRAFT COMPANY	U206G	Charter	Passenger	OCTA	G	During the initial climb, the alternator failed.
3/12/09	200907676	Incident	No	Bathurst Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTAF	G	The aircraft entered and backtracked the runway while another aircraft was on short final.
4/12/09	200907643	Incident	No	Newman Aerodrome, S M 74Km	WA	THE BOEING COMPANY	717-200	Air Transport High Capacity	Passenger	OCTA	G	During the descent, the aircraft was struck by lightning. The aircraft was returned to Perth.
4/12/09	200907654	Incident	No	Sydney Aerodrome, NE M 93Km	NSW	THE BOEING COMPANY	777-208/ER	Air Transport High Capacity	Passenger	CTA	A	Shortly after takeoff, the crew reported a hydraulic leak and the aircraft was returned for a landing after dumping fuel.
4/12/09	200907655	Incident	No	near Cape Melville (HLS)	QLD	CESSNA AIRCRAFT COMPANY	441	General Aviation-Unknown	Unknown	CTA	A	The aircraft was cleared to climb to FL320 but was observed by ATC to climb through FL323 without a clearance.
4/12/09	200907659	Incident	No	Mackay Aerodrome, 350° M 11Km	QLD	PIPER AIRCRAFT CORP	PA-28-140	General Aviation-Unknown	Unknown	CTA	D	While the aircraft was inbound, the radio failed. The pilot contacted ATC with a mobile phone.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
4/12/09	200907660	Incident	No	Adelaide Aerodrome, 337° M 31Km	SA	Evektor	Sportstar	Sports Aviation	Unknown	CTA	C	The aircraft was observed by ATC to have climbed into controlled airspace without a clearance.
4/12/09	200907661	Incident	No	Gold Coast Aerodrome, NW M 11Km	QLD	CESSNA AIRCRAFT COMPANY	172M	General Aviation-Unknown	Unknown	CTR	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
4/12/09	200907664	Incident	No	Launceston Aerodrome	TAS	Unknown	Unknown	Air Transport High Capacity	Passenger	CTR	D	During the take-off run, the aircraft struck a finch.
4/12/09	200907665	Incident	No	ELATI (IFR)	Other	AIRBUS INDUSTRIE	A330-223	Air Transport High Capacity	Passenger	OCA	A	Late co-ordination details were passed from the Colombo controller to the Indian sector controller for the aircraft approaching the FIR boundary.
4/12/09	200907666	Incident	No	Porpuraaw Aerodrome	NT	CESSNA AIRCRAFT COMPANY	402C	Charter	Passenger	CTAF	G	During the take-off run, the aircraft struck a bird. The takeoff was rejected.
4/12/09	200907668	Incident	No	EGATU (IFR)	Other	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	OCA	A	An incorrect boundary estimate was coordinated from Ujung Pandang controller to Brisbane ATC for an aircraft approaching the FIR boundary.
4/12/09	200907670	Incident	No	Broome Aerodrome	WA	CESSNA AIRCRAFT COMPANY	210L	Charter	Unknown	CTAF (R)	G	During the landing roll, the aircraft struck a kestrel.
4/12/09	200907671	Incident	No	Brisbane Aerodrome, 307° M 11Km	QLD	BELL HELICOPTER CO	47G-4	General Aviation-Unknown	Unknown	CTR	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
4/12/09	200907672	Incident	No	Adelaide Aerodrome	SA	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTR	C	While taxiing on taxiway A, the aircraft struck a kestrel that impacted the left propeller.
4/12/09	200907673	Incident	No	Adelaide Aerodrome	SA	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck three kestrels.
4/12/09	200907678	Incident	No	Moorabbin Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-34-200T	General Aviation-Unknown	Unknown	GAAP	GAAP	During the approach, the pilot reported an unsafe landing gear indication. The pilot conducted the non-normal checklist and landed.
4/12/09	200907687	Incident	No	Tindal Aerodrome	NT							The Tindal radar was returned to service 30 minutes after the time specified in the NOTAM.
4/12/09	200907688	Incident	No	near Darwin Aerodrome	NT	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTR	C	During the final approach, the aircraft struck a bird that impacted the fuselage.
4/12/09	200907689	Incident	No	Launceston Aerodrome	TAS	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	D	During the initial climb from runway 32L, the aircraft struck a finch.
4/12/09	200907690	Incident	No	Tindal Aerodrome	NT							Tindal radar had intermittent failures.
4/12/09	200907691	Incident	No	Melbourne Aerodrome	VIC	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	The crew did not comply with an instruction to hold short of a taxiway.
4/12/09	200907692	Incident	No	Melbourne Aerodrome, 310° M 56Km	VIC	CESSNA AIRCRAFT COMPANY	TU206G	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
4/12/09	200907693	Incident	No	Bathurst Aerodrome, E M 46Km	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	CTA	C	An unidentified aircraft was observed by ATC to have entered R520A without a clearance.
4/12/09	200907709	Incident	No	Parafield Aerodrome, 252° M 13Km	SA	Unknown	Unknown	General Aviation-Unknown	Unknown	CTR	C	The unidentified aircraft was observed by ATC entering controlled airspace without clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
4/12/09	200907710	Incident	No	Newcastle Regional Heliport (HLS), 264° M 6Km	NSW	CESSNA AIRCRAFT COMPANY	210F	Private	Pleasure / Travel	CTAF	G	During the initial climb, the landing gear failed to retract. The pilot diverted to Scone, and conducted a wheels up landing.
4/12/09	200907711	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-8BK	Air Transport High Capacity	Passenger	CTR	C	While taxiing after landing, the aircraft did not taxi in accordance with the published procedures.
4/12/09	200907717	Incident	No	Gold Coast Aerodrome, 105° M 11Km	NSW	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	C	On departure, the aircraft was assigned a heading of 140 degrees. The aircraft was subsequently observed by ATC to have turned onto a heading of 210 degrees without a clearance.
4/12/09	200907719	Incident	No	RAINY (IFR)	QLD	THE BOEING COMPANY	737-86N	Air Transport High Capacity	Passenger	CTA	C	The crew had been issued a RWY 15 BIBOOHRA ONE ALPHA STAR. The crew did not comply with the tracking requirement as specified in the procedure.
4/12/09	200907850	Incident	No	London Heathrow	Other	AIRBUS INDUSTRIE	A380-842	Air Transport High Capacity	Passenger	Other	Foreign	During the landing roll, the nose wheel steering failed.
5/12/09	200907667	Incident	No	near Mangalore Aerodrome	VIC	Alpi Aviation	Pioner 300	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R351 and R350 without a clearance.
5/12/09	200907712	Incident	No	near Darwin Aerodrome	NT	AIRBUS INDUSTRIE	A321-231	Air Transport High Capacity	Passenger	CTR	C	During the final approach, the aircraft struck a bird that impacted the the fuselage.
5/12/09	200907713	Incident	No	Hobart Aerodrome	TAS	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	D	During the landing, the aircraft struck a bird.
5/12/09	200907715	Incident	No	TASHA (IFR)	QLD	BOMBARDIER INC	BD-700-1A10	General Aviation-Unknown	Unknown	CTA	A	During the cruise, the crew did not track in accordance with the cleared and planned route.
5/12/09	200907716	Incident	No	Rockhampton Aerodrome	QLD	RAYTHEON AIRCRAFT COMPANY	G36	General Aviation-Unknown	Unknown	CTA	D	A loss of separation assurance occurred between a Beech 36 maintaining 6,000 ft and an Airbus A320 (A320) departing on climb. The A320's original departure instruction to climb to 7,000 ft was amended to 5,000 ft, but the amendment was not passed to the crew until the A320 passed 4,000 ft.
						AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger			
5/12/09	200907718	Incident	No	near Bankstown Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-28-151	General Aviation-Unknown	Unknown	GAAP	GAAP	The pilot was instructed to maintain 1,500 ft and join crosswind but subsequently was observed by ATC joining final for runway 11 without a clearance.
5/12/09	200907721	Incident	No	Bankstown Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-28-161	General Aviation-Unknown	Unknown	GAAP	GAAP	During the approach, the aircraft was cleared by ATC to maintain 1,500 ft. The aircraft subsequently descended to 1,000 ft without a clearance.
5/12/09	200907722	Incident	No	Mackay Aerodrome, 169° M 37Km	QLD	ROBINSON HELICOPTER CO	R44	General Aviation-Unknown	Unknown	CTA	D	The helicopter was observed by ATC to have entered controlled airspace without a clearance.
5/12/09	200907723	Incident	No	Bankstown Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-44-180	General Aviation-Unknown	Unknown	GAAP	GAAP	During the initial climb, the pilots window detached from the aircraft. The aircraft was returned to Bankstown.
5/12/09	200907725	Incident	No	Adelaide Aerodrome, 340° M 28Km	SA	NANCHANG AIRCRAFT MANUFACTURING	CJ-6A	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
5/12/09	200907726	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During taxi, the crew noticed clear plastic film pass under the the aircraft.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
5/12/09	200907727	Incident	No	Adelaide Aerodrome, 325° M 65Km	SA	NANCHANG AIRCRAFT MANUFACTURING	CJ-6A	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R295A without a clearance.
5/12/09	200907728	Incident	No	near Rockhampton Aerodrome	QLD	BEECH AIRCRAFT CORP	A36	General Aviation-Unknown	Unknown	CTR	D	During the final approach, the aircraft struck a bird.
5/12/09	200907729	Incident	No	near Beaudesert Hospital (HLS)	QLD	KAVANAGH BALLOONS	E-260	Ballooning	Other	OCTA	G	During the landing, the balloon's envelope was pierced by a tree branch, resulting in minor damage.
5/12/09	200907730	Incident	No	Sydney Aerodrome, 159° M 15Km	NSW	MCDONNELL DOUGLAS	MD-11F	Air Transport High Capacity	Freight	CTA	C	The crew had been issued a RWY 16R KAMPI ONE SID. The crew did not comply with the tracking requirement as specified in the procedure.
5/12/09	200907731	Incident	No	Canberra Aerodrome, 273° M 6Km	ACT	KAVANAGH BALLOONS	B-350	Ballooning	Other	CTR	C	During the approach, the balloon struck a suspension cable supporting an outdoor sculpture.
5/12/09	200907732	Incident	No	Brisbane Aerodrome	QLD	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft struck a bird that impacted the left propeller.
5/12/09	200907737	Incident	No	Brisbane Aerodrome	QLD	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	CTR	C	The crew rejected the take-off run due to a nosewheel vibration.
5/12/09	200907738	Incident	No	Whyalla Aerodrome	SA	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTAF (R)	G	During the take-off run, the aircraft struck a bird that impacted the windscreen.
5/12/09	200907740	Incident	No	near Melbourne Aerodrome	VIC	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTA	A	During the cruise, cabin crew detected fumes in the forward galley. During the subsequent engineering inspection, the fault could not be reproduced.
5/12/09	200907741	Incident	No	near Brisbane Aerodrome	QLD	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTA	C	While on climb, the aircraft was struck by lightning.
5/12/09	200907752	Incident	No	Bacchus Marsh Township (VFR), N M 7Km	VIC	Unknown AMATEUR BUILT AIRCRAFT	Unknown LANCAIR 320	Unknown Unknown	Unknown Unknown	OCTA	G	While descending OCTA, the pilot of the Lancair 320 observed an unidentified aircraft pass 200 metres to the left and 100 ft below.
5/12/09	200907790	Incident	No	Launceston Aerodrome, 267° M 81Km ('The Vale' Mount Roland)	TAS	S.O.C.A.T.A.-GROUPE AEROSPATIALE	TB-10	General Aviation-Unknown	Unknown	OCTA	G	Immediately after rotation for takeoff, the pilot noticed that the engine was not developing normal climb power. The pilot carried out a precautionary landing in a paddock but during the landing roll, the aircraft impacted a fence. Post flight inspection revealed two fouled spark plugs.
6/12/09	200907733	Incident	No	near Singleton (NDB)	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R564A without a clearance.
6/12/09	200907734	Incident	No	near Singleton (NDB)	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R564A without a clearance.
6/12/09	200907735	Incident	No	Adelaide Aerodrome, 330° M 37Km	SA	DE HAVILLAND AIRCRAFT PTY LTD	DHC-1 MK 22	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
6/12/09	200907736	Incident	No	near Williamtown Aerodrome	NSW	THE BOEING COMPANY	737-7Q8	Air Transport High Capacity	Passenger	CTA	E	The aircraft was observed by ATC to have entered class E controlled airspace without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
6/12/09	200907742	Incident	No	Maroochydore/ Sunshine Coast Aerodrome, N M 20Km	QLD	CESSNA AIRCRAFT COMPANY	172S	General Aviation- Unknown	Unknown	CTA	D	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
6/12/09	200907743	Incident	No	Parafield Aerodrome	SA	GROB - BURKHAAFT FLUGZEUGBAU	G-115	General Aviation- Unknown	Unknown	GAAP	GAAP	The aircraft struck a bird.
6/12/09	200907744	Incident	No	Mackay Aerodrome, 150° M 93Km	QLD	EMBRAER- EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTA	E	While the aircraft was on descent, the crew transferred from the en route frequency to the tower frequency without a clearance.
6/12/09	200907753	Incident	No	Bankstown Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	152	General Aviation- Unknown	Unknown	GAAP	GAAP	The Piper PA-28 drifted right after takeoff and the Cessna 152 drifted left after takeoff. The Tower controller issued a traffic alert the pilots.
						PIPER AIRCRAFT CORP	PA-28-181	General Aviation- Unknown	Unknown			
6/12/09	200907755	Accident	No	Augusta (ALA), E M 28Km	WA	TECNAM - C. AERONAUTICHE SRL	P2002 SIERRA	Flying Training	Training Solo	OCTA	G	During the solo navigation exercise, the pilot reported uncertain of position due to reduced visibility in smoke. ATC advised the pilot to fly north out of the smoke and then head to the coast. Subsequently the pilot reported clear of smoke but uncertain of fuel remaining. The pilot conducted a precautionary landing. During the landing roll, the aircraft struck a ditch and was seriously damaged. The pilot suffered serious injuries.
6/12/09	200907757	Incident	No	near Bankstown Aerodrome	NSW	ROBINSON HELICOPTER CO	R44	General Aviation- Unknown	Unknown	GAAP	GAAP	During the approach, the Robinson R44 (R44) did not maintain 1,800 ft, as required by published procedures. The R44 passed in close proximity to a Piper PA-28 on downwind.
						PIPER AIRCRAFT CORP	PA-28-151	General Aviation- Unknown	Unknown			
6/12/09	200907762	Incident	No	near Moorabbin Aerodrome	VIC	CESSNA AIRCRAFT COMPANY	172N	General Aviation- Unknown	Unknown	OCTA	G	The pilot did not contact Moorabbin Tower prior to tracking along the edge of the GAAP control zone, as required in the published procedures.
6/12/09	200907764	Incident	No	Melbourne Aerodrome, 018° M 31Km	VIC	Unknown	Unknown	Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
6/12/09	200907765	Incident	No	DUBEV (IFR)	Other	THE BOEING COMPANY	767-3X2/ER	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the crew did not amend a waypoint estimate for DUBEV and the aircraft passed DUBEV three minutes late.
6/12/09	200907767	Incident	No	Coffs Harbour Aerodrome, 180° M 15Km	NSW	RAYTHEON AIRCRAFT COMPANY	B200	Aerial Work	EMS	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
6/12/09	200907772	Incident	No	Griffith Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	404	Unknown	Unknown	CTAF (R)	G	During a circuit prior to landing, the crew received a TCAS TA followed by a TCAS RA. Radio communications with the traffic were not established until the aircraft had landed.
						S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger			
6/12/09	200907775	Accident	No	near Yarrawonga Aerodrome	VIC	Unknown	Unknown	Sports Aviation	Other	CTAF	G	The ultralight was reported to have collided with terrain. Both occupants sustained fatal injuries and the aircraft was destroyed.
6/12/09	200907806	Incident	No	Camden Aerodrome	NSW	ROBINSON HELICOPTER CO	R44 II	General Aviation- Unknown	Unknown	GAAP	GAAP	While tracking to Bankstown, the helicopter infringed the Camden control zone buffer zone.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
6/12/09	200907883	Accident	No	Heck Field (ALA)	QLD	Skyfox Aviation	Gazelle Ca25n	Sports Aviation	Unknown	OCTA	G	During the climb, the rudder cable failed and the ultralight collided with terrain. The pilot sustained minor injuries and the passenger sustained serious injuries.
7/12/09	200907746	Incident	No	Jakarta International Airport	Other	AIRBUS INDUSTRIE	A330-203	Air Transport High Capacity	Passenger	Other	Foreign	During the flare, the aircraft struck a bird.
7/12/09	200907748	Incident	No	near Maroochydore/ Sunshine Coast Aerodrome	QLD	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	D	During short final approach, the aircraft struck a bird that impacted the nose cone.
7/12/09	200907749	Incident	No	Tindal Aerodrome	NT							The Tindal radar failed due to what appeared to be a gearbox problem.
7/12/09	200907750	Incident	No	Sydney Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTR	C	A bird carcass was retrieved from runway 34L.
7/12/09	200907751	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a crow.
7/12/09	200907758	Incident	No	Brisbane Aerodrome, 275° M 46Km	QLD	CESSNA AIRCRAFT COMPANY	182K	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R660B without a clearance.
7/12/09	200907759	Incident	No	OPABA (IFR)	NT	THE BOEING COMPANY	747-467	Air Transport High Capacity	Passenger	OCA	A	After the crew reported regaining track, ATC observed the aircraft to be 9 NM to the right of track without a clearance.
7/12/09	200907766	Incident	No	Moorabbin Aerodrome	VIC	CESSNA AIRCRAFT COMPANY	U206G	Flying Training	Training Dual	GAAP	GAAP	On departure, burning grass fumes were detected in the cockpit. The aircraft was returned to Moorabbin. The pilot suspected the fumes to be from remaining birds nest previously removed from the heater shroud vents.
7/12/09	200907770	Incident	No	Bankstown Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	182Q	General Aviation-Unknown	Unknown	GAAP	GAAP	The aircraft crossed runway 29R without a clearance.
7/12/09	200907776	Incident	No	CULIN (IFR)	NSW	RAYTHEON AIRCRAFT COMPANY	HAWKER 800XP	Charter	Unknown	CTA	C	The aircraft entered a right holding pattern instead of the published left pattern.
7/12/09	200907777	Incident	No	Parafield Aerodrome	SA	AMATEUR BUILT AIRCRAFT	VAN'S RV-6A	General Aviation-Unknown	Unknown	CTAF (R)	G	The aircraft landed on runway 03R during CTAF hours of operation, during which the runway is published as not available.
7/12/09	200907779	Incident	No	Moruya Aerodrome	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTA	E	The controller cleared the aircraft to descend to FL120 and one minute later cleared the aircraft to descend to FL110 with VFR traffic at 9,500 ft. The controller immediately realised the error and cancelled the clearance to FL110 but the crew did not respond to the transmission. A further minute later, the aircraft left FL120. The controller subsequently confirmed the clearance to FL110.
7/12/09	200907780	Incident	No	Perth Aerodrome, 300° M 26Km	WA	PIPER AIRCRAFT CORP	PA-44-180	Flying Training	Training Dual	CTA	C	The Piper PA-44 was instructed to maintain 2,000 ft but was climbed to 2,300 ft without a clearance. This resulted in a breakdown in separation with a Fokker F27. Separation reduced to 700 ft and 2.3 NM.
						FOKKER B.V.	F27 MK 50	Charter	Unknown			
7/12/09	200907782	Incident	No	near Avalon Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-28-181	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace twice without a clearance.
7/12/09	200907784	Incident	No	Nauru International Airport	Other	THE BOEING COMPANY	737-33A	Air Transport High Capacity	Passenger	Other	Foreign	The Nauru controller did not coordinate the aircraft's departure details with the Brisbane controller.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
7/12/09	200907787	Incident	No	Parafield Aerodrome	SA	S.O.C.A.T.A.-GROUPE AEROSPATIALE	TB-10	General Aviation-Unknown	Unknown	GAAP	GAAP	During the landing, the aircraft struck a bird.
7/12/09	200907788	Incident	No	near Lancelin Township (VFR)	WA	BEECH AIRCRAFT CORP	A36	Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R146A without a clearance.
7/12/09	200907792	Incident	No	Edinburgh Aerodrome	SA	CESSNA AIRCRAFT COMPANY	340A	General Aviation-Unknown	Unknown	CTR	C	The aircraft was observed by ATC to have entered the Edinburgh military control zone without clearance.
7/12/09	200907793	Incident	No	Brisbane Aerodrome, 020° M 7Km	QLD	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTR	C	While departing on a SID, the crew did not comply with the published route.
7/12/09	200907794	Incident	No	Cairns Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the landing roll on runway 15, the aircraft struck a bird that impacted the nose area.
7/12/09	200907797	Incident	No	Holsworthy Aerodrome	NSW	Bell Helicopter	214B-1	General Aviation-Unknown	Unknown	PRD	PRD	The helicopter was observed by ATC to have entered R555C without a clearance.
7/12/09	200907798	Incident	No	Honiara Aerodrome	Other	GATES LEARJET CORP	36A	Aerial Work	EMS	OCTA	G	The Honiara Flight Service operator did not provide departure advice to the Solomon Sector controller for an aircraft departing Honiara.
7/12/09	200907816	Incident	No	Townsville Aerodrome	QLD	BELL HELICOPTER CO	206	Unknown	Unknown	CTR	C	The helicopter was cleared to take off to the south, but was observed by ATC departing in a northerly direction.
8/12/09	200907745	Incident	No	OPABA (IFR)	NT	THE BOEING COMPANY	767-319	Air Transport High Capacity	Passenger	OCA	A	The crew reported at the Brisbane FIR boundary right of assigned track without a clearance. The crew had requested a deviation due to weather but the Ujung controller had not issued the deviation due to poor radio communication.
8/12/09	200907747	Incident	No	PUPEB (IFR), N M 75Km	QLD	THE BOEING COMPANY	737-824	Air Transport High Capacity	Passenger	CTA	A	The aircraft was observed by ATC to be 6 NM left of the assigned track without a clearance.
8/12/09	200907760	Incident	No	Cairns Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	402C	General Aviation-Unknown	Unknown	CTR	C	The aircraft was observed by ATC taxiing along taxiway A without a taxi clearance.
8/12/09	200907761	Incident	No	Mackay Aerodrome, 265° M 17Km	QLD	PIPER AIRCRAFT CORP	PA-28-180	General Aviation-Unknown	Unknown	CTA	D	The aircraft was observed by ATC to be left of assigned track without a clearance.
8/12/09	200907763	Incident	No	Brisbane Aerodrome, N M 33Km	QLD	CESSNA AIRCRAFT COMPANY	172N	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
8/12/09	200907771	Incident	No	ENPIT (IFR)	WA	THE BOEING COMPANY	747-236	Air Transport High Capacity	Freight	CTA	A	Late co-ordination details were passed by Brisbane ATC to Melbourne ATC for an aircraft approaching the common airspace boundary.
8/12/09	200907773	Incident	No	Brisbane Aerodrome	QLD	THE BOEING COMPANY	767-336	Air Transport High Capacity	Passenger	CTR	C	During pushback, cabin crew detected oily fumes in the galley. After the air-conditioning packs were turned on, the fumes dissipated.
8/12/09	200907774	Incident	No	Alice Springs Aerodrome, WNW M 93Km	NT	PILATUS AIRCRAFT LTD	PC-12/45	Aerial Work	EMS	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
8/12/09	200907778	Incident	No	Edinburgh Aerodrome, E M 6Km	SA	PIPER AIRCRAFT CORP	PA-28-181	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R265A without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
8/12/09	200907785	Incident	No	Sydney Aerodrome, 240° M 24Km	NSW	PIPER AIRCRAFT CORP	PA-28-181	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft was observed by ATC to have entered R555C without a clearance.
8/12/09	200907786	Incident	No	Kingscote Aerodrome	SA	Unknown	Unknown	Unknown	Unknown	CTAF (R)	G	During a routine runway inspection, a plover carcass was retrieved.
8/12/09	200907789	Incident	No	PANKI (IFR)	SA	THE BOEING COMPANY	737-7BX	Air Transport High Capacity	Passenger	CTA	A	The Taillem Bend controller did not provide complete coordination to the adjacent sector controller for an aircraft approaching the common airspace boundary.
8/12/09	200907791	Incident	No	Gold Coast Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	208	Charter	Unknown	CTAF (R)	G	The aircraft departed from a closed runway.
8/12/09	200907799	Incident	No	Brisbane Aerodrome, 142° M 37Km	QLD	PIPER AIRCRAFT CORP	PA-31	General Aviation-Unknown	Unknown	CTA	C	On descent, the aircraft was cleared to 4,000 ft but was observed by ATC to descend to 3,600 ft without a clearance.
8/12/09	200907809	Incident	No	Mount Isa Aerodrome, 162° M 4Km	QLD	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTAF (R)	G	After descending through an area of thermal activity at 800 ft AGL, the aircraft's rate of descent increased to 1,600 ft/min. The approach was stabilised by 500 ft AGL.
8/12/09	200907811	Incident	No	Learmonth Aerodrome	WA	AEROSPATIALE INDUSTRIES	AS.332L	Charter	Passenger	CTAF (R)	G	During passenger boarding, a passenger noticed smoke emanating from the cabin ceiling. An investigation revealed that the cabin fluoro light tube was arcing due to a loose fit in the socket. The smoke dissipated when the light was switched off.
8/12/09	200907820	Incident	No	near Los Angeles International Airport	Other	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	Other	Foreign	During the initial climb and flap retraction, the crew received a flap asymmetry warning and actioned the non-normal checklist. Fuel was dumped and the aircraft was returned to Los Angeles.
8/12/09	200907822	Incident	No	Adelaide Aerodrome	SA							An air compressor filter housing was dropped from a tug onto taxiway A6.
8/12/09	200907851	Incident	No	GUTEV (IFR)	Other	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	OCA	A	During cruise, the left windscreen cracked. The aircraft diverted to Brisbane.
9/12/09	200907754	Incident	No	near Byron Bay (VFR)	NSW	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTA	C	As the aircraft descended through FL150, the crew noticed a strong oil smell on the flight deck and the pilot-in-command developed nausea and light-headedness. The crew reduced the flight deck temperature and the smell gradually dissipated.
9/12/09	200907781	Incident	No	near Bundaberg Aerodrome	QLD	RAYTHEON AIRCRAFT COMPANY	B200	Aerial Work	EMS	CTAF (R)	G	The aircraft was observed by ATC to have climbed through the assigned level without a clearance.
9/12/09	200907783	Incident	No	Brisbane Aerodrome, 250° M 11Km	QLD	PIPER AIRCRAFT CORP	PA-24-400	General Aviation-Unknown	Unknown	CTR	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
9/12/09	200907800	Incident	No	Bankstown Aerodrome	NSW	AMATEUR BUILT AIRCRAFT	SEAREY	General Aviation-Unknown	Unknown	GAAP	GAAP	The pilot did not request a start clearance before commencing to taxi for takeoff.
9/12/09	200907802	Incident	No	GUTEV (IFR), 150° M 15Km	Other	AIRBUS INDUSTRIE	A340-313X	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the aircraft diverted to the left of track without a clearance.
9/12/09	200907813	Incident	No	Parafield Aerodrome	SA	GROB - BURKHAART FLUGZEUGBAU	G-115	General Aviation-Unknown	Unknown	GAAP	GAAP	During the take-off run, the aircraft struck two birds.
9/12/09	200907814	Incident	No	Avalon Aerodrome	VIC	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	During the takeoff, the aircraft struck a bird.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
9/12/09	200907815	Incident	No	Canberra Aerodrome	ACT	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	On rotation, the aircraft struck a galah.
9/12/09	200907817	Incident	No	Moorabbin Aerodrome	QLD	PIPER AIRCRAFT CORP	PA-28R-180	General Aviation-Unknown	Unknown	GAAP	GAAP	The pilot of a Piper PA-28 did not comply with the taxi instruction and subsequently entered runway 31L without a clearance, resulting in an infringement of runway separation standards with another Piper PA-28 taking off from runway 31L. The departing aircraft crossed over the taxiing aircraft at 100 ft.
						PIPER AIRCRAFT CORP	PA-28-151	General Aviation-Unknown	Unknown			
9/12/09	200907823	Incident	No	Sydney Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTR	C	While driving on taxiway C, the safety officer retrieved a kestrel carcass.
9/12/09	200907824	Incident	No	Melbourne Aerodrome	VIC	Unknown	Unknown	Unknown	Unknown	CTR	C	During an inspection of runway 34, the safety officer retrieved the carcass of a Richard's pipit.
9/12/09	200907825	Incident	No	Amberley Aerodrome, SW M 37Km	QLD	CIRRUS DESIGN CORPORATION	SR20	Unknown	Unknown	PRD	PRD	At the pilot's request, ATC assigned the aircraft 5,000 ft, but the radar lowest safe altitude for the route is 5,100 ft. The aircraft was subsequently assigned 5,100 ft.
9/12/09	200907827	Incident	No	MUBIT (IFR), 180° M 144Km	Other	AIRBUS INDUSTRIE	A330-323X	Air Transport High Capacity	Passenger	OCA	A	The aircraft was cleared by ATC to divert up to 20NM left of track and the crew were instructed to report back on route. The crew reported back on route while the aircraft was still left of track.
9/12/09	200907828	Incident	No	Mackay Aerodrome, 313° M 19Km	QLD	CESSNA AIRCRAFT COMPANY	R182	General Aviation-Unknown	Unknown	CTA	D	During the cruise, the pilot was not in normal communications with ATC.
9/12/09	200907831	Incident	No	near Mumbai International Airport	Other	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	Other	Foreign	During cruise, the cabin crew noticed a strong burning smell in the cabin. The non-normal checklist was actioned and the upper deck recirculation fan was selected off, resulting in the fumes dissipating.
9/12/09	200907832	Incident	No	CHAMP (IFR)	NSW	MCDONNELL DOUGLAS CORPORATION	F/A-18	Military	Other	CTA	A	During the cruise, the crew did not track in accordance with the planned and cleared route.
9/12/09	200907837	Incident	No	Mundaring Weir (VFR)	WA	CESSNA AIRCRAFT COMPANY	210M	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
9/12/09	200907838	Incident	No	Brooklands (ALA)	QLD	CESSNA AIRCRAFT COMPANY	182E	Sports Aviation	Parachute Operations	CTA	C	The pilot conducted a parachute drop plus commenced descent without a clearance.
9/12/09	200907839	Incident	No	Yarrowee (NDB/VOR)	VIC	CESSNA AIRCRAFT COMPANY	550	General Aviation-Unknown	Unknown	CTA	A	During an IFR flight in controlled airspace, the aircraft lost VHF communications with ATC for 32 minutes.
9/12/09	200907840	Incident	No	overhead Karratha Aerodrome	WA	Airbus Industrie	A320-216	Air Transport High Capacity	Passenger	CTA	C	The crew did not comply with an instruction to reach FL 360 by MONEY. The crew subsequently reported at MONEY at FL 350.
9/12/09	200907841	Incident	No	Jandakot Aerodrome	WA	PILATUS AIRCRAFT LTD	PC-12/45	Aerial Work	EMS	GAAP	GAAP	The aircraft crossed the threshold of runway 06R without clearance.
9/12/09	200907842	Incident	No	near Parafield Aerodrome	SA	BEECH AIRCRAFT CORP	76	Flying Training	Training Dual	OCTA	G	During aerial work, the landing gear failed to retract. The aircraft returned to Parafield. The subsequent engineering inspection revealed that the roll pin on a plug in the hydraulic actuator had failed causing the plug to be displaced, resulting in a hydraulic leak.
9/12/09	200907843	Incident	No	Melbourne Aerodrome	VIC	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTR	C	The crew did not comply with the issued taxi instructions.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
9/12/09	200907845	Incident	No	Singapore Changi International	Other	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	Other	Foreign	During landing, the aircraft struck a bird that impacted the left side of the fuselage.
9/12/09	200907846	Incident	No	BENZO (IFR), 148° M 69Km	TAS	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the aircraft climbed 300 ft without a clearance.
9/12/09	200907847	Incident	No	Essendon Aerodrome	VIC	CESSNA AIRCRAFT COMPANY	404	Charter	Passenger	CTR	C	During the take-off run, the pilot noticed a door unsafe indication and rejected the takeoff.
9/12/09	200907849	Incident	No	Williamtown Aerodrome, S M 15Km	NSW	JETSTREAM AIRCRAFT LTD	3206	Air Transport Low Capacity	Passenger	CTA	C	During the descent, the aircraft struck a bird that impacted the windscreen.
9/12/09	200907852	Incident	No	MEPAB (IFR)	Other	THE BOEING COMPANY	737-8Q8	Air Transport High Capacity	Passenger	OCA	A	Incorrect coordination details were passed from the Nadi controller to the Brisbane controller on an aircraft approaching the FIR boundary.
10/12/09	200907805	Incident	No	Dochra Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	PRD	PRD	An unidentified aircraft was observed by ATC to have entered R564A without a clearance.
10/12/09	200907819	Incident	No	Canberra Aerodrome	ACT	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTR	C	During the take-off run, the aircraft struck a galah.
10/12/09	200907829	Serious Incident	No	Barwon Heads/Geelong (ALA), W M 6Km	VIC	CESSNA AIRCRAFT COMPANY	152	Private	Pleasure / Travel	OCTA	G	During the initial climb, the engine failed. The pilot conducted a forced landing in a nearby paddock. No injuries occurred and the aircraft was not damaged.
10/12/09	200907830	Incident	No	near Sydney Aerodrome	NSW	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTA	C	During the initial climb, the aircraft climbed through the assigned altitude without a clearance.
10/12/09	200907853	Incident	No	Bankstown Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-31-325	Charter	Unknown	GAAP	GAAP	During the approach, the pilot did not comply with the published procedures.
10/12/09	200907869	Incident	No	Archerfield Aerodrome, 045° M 7Km	QLD	CIRRUS DESIGN CORPORATION	SR20	General Aviation-Unknown	Unknown	CTA	C	The pilot did not comply with an ATC instruction to leave the GAAP zone at 1,000 ft and the aircraft was subsequently observed to have entered C class controlled airspace without a clearance.
10/12/09	200907870	Incident	No	Coffs Harbour Aerodrome	NSW	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTR	D	During the landing roll on runway 03, the aircraft struck a bird.
10/12/09	200907871	Incident	No	Canberra Aerodrome	ACT	PIPER AIRCRAFT CORP	PA-31-350	Charter	Unknown	CTR	C	The crew had been issued a RWY 35 CANBERRA SIX RADAR SID. The crew did not comply with the tracking requirement as specified in the procedure.
10/12/09	200907903	Accident	No	Warnervale (ALA)	NSW	GRUMMAN AMERICAN AVIATION CORP	GA-7	Private	Pleasure / Travel	CTAF	G	During the landing roll on runway 20, the aircraft struck a wallaby that impacted the nose landing gear, causing it to collapse.
11/12/09	200907714	Accident	No	Toowoomba Aerodrome, SW M 9Km ('Wellcamp')	QLD	ROBINSON HELICOPTER CO	R22 BETA	Private	Pleasure / Travel	OCTA	G	On base, the helicopter encountered a stronger downwind component than the pilot expected. The pilot's attempt to arrest the high descent rate resulted in low rotor RPM and the helicopter landed on a raised garden and subsequently rolled off a retaining wall sustaining serious damage.
11/12/09	200907833	Incident	No	Adelaide Aerodrome	SA	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck two galahs that impacted the nose landing gear.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information.



Occurrences Entered into the ATSB Aviation Safety Database
Between 12 December 2009 and 18 December 2009

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
11/12/09	200907834	Incident	No	Williamtown Aerodrome	NSW	THE BOEING COMPANY	737-7Q8	Air Transport High Capacity	Passenger	CTR	C	No taxi details had been coordinated by Williamtown ATC to Melbourne ATC.
11/12/09	200907835	Incident	No	near Sydney Aerodrome	NSW	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During final approach, the aircraft struck a bird that impacted the left wing.
11/12/09	200907873	Incident	No	Parafield Aerodrome, 039° M 4Km	SA	PIPER AIRCRAFT CORP	PA-28-181	General Aviation-Unknown	Unknown	CTA	C	The aircraft was observed by ATC to have entered C class controlled airspace without a clearance.
11/12/09	200907877	Incident	No	Launceston Aerodrome	TAS	THE BOEING COMPANY	737-8BK	Air Transport High Capacity	Passenger	CTR	D	During the take-off run on runway 32L, the aircraft struck a plover.
11/12/09	200907880	Incident	No	Brisbane Aerodrome, 230° M 9Km	QLD	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft was cleared to 2,000 ft. The aircraft was subsequently observed by ATC to have descended below 2,000 ft without a clearance.
11/12/09	200907881	Incident	No	DAYBO (IFR)	QLD	Unknown	Unknown	Unknown	Unknown	CTA	C	An unidentified aircraft was observed by ATC to have entered controlled airspace without a clearance.
11/12/09	200907882	Incident	No	Katoomba (NDB), 275° M 37Km	NSW	CESSNA AIRCRAFT COMPANY	441	Aerial Work	Fire Control	CTA	A	During the cruise, the crew did not track in accordance with the cleared route.
12/12/09	200907724	Incident	No	Brisbane Aerodrome	QLD	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a large bird.
12/12/09	200907836	Incident	No	Williamtown Aerodrome, N M 9Km	NSW	RAYTHEON AIRCRAFT COMPANY	B200	Aerial Work	EMS	CTA	E	The aircraft was observed by ATC to have entered controlled airspace without a clearance.
12/12/09	200907879	Incident	No	Mackay Aerodrome	QLD	Unknown	Unknown	Unknown	Unknown	CTAF (R)	G	During a routine runway inspection, a turtle dove carcass was retrieved from runway 05.
13/12/09	200907720	Accident	No	Rockhampton Aerodrome, N M 11Km	QLD	AMERICAN AIRCRAFT CORP	AA-5B	Private	Pleasure / Travel	OCTA	G	While taxiing, the pilot exited the aircraft to chase cattle off the runway, leaving the engine running. The aircraft subsequently rolled forward and impacted trees, resulting in serious damage.
13/12/09	200907878	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the take-off run, the aircraft struck a bird.
15/12/09	200907812	Incident	Yes	KONIL (IFR)	WA	DE HAVILLAND CANADA	DHC-8-102	Air Transport Low Capacity	Unknown	CTA	E	During cruise, a decompression occurred. The crew carried out a descent to 8,000 ft and returned the aircraft to Perth. The investigation is continuing.
15/12/09	200907890	Accident	No	Moorabbin Aerodrome	VIC	ROBINSON HELICOPTER CO	R44 II	Flying Training	Training Solo	GAAP	GAAP	During takeoff, the solo student pilot lost control of the helicopter and a skid contacted the ground before the helicopter rolled onto its side. The pilot was uninjured, but the helicopter was seriously damaged.