COMMONWEALTH OF AUSTRALIA DEPARTMENT OF CIVIL AVIATION

AIRCRAFT ACCIDENT INVESTIGATION SUMMARY REPORT

Reference No.

1. LOCATION OF OCCURRENCE Tenterfield Golf Course, New South Wales			Height o.m.s.l. (ft) 2000 feet	Date 23,8,69	Time (Locol) 1530	Zone EST
THE AIRCRAFT			•			
Make and Model Grumman G164A 450 "A	g-cat''	Registration VH-CCS	Certificate of Airworthiness	Valid from Valid to 12.11.68 11.11.		77
Registered Owner Cropcair Aviation Pty. Ltd.,		Operator Cropcair Aviation Pty. Ltd.,		Degree of damage to aircroft Substantial		
G.P.O. Box 1432,		G.P.O. Box 1432,		Other property damaged		
Brisbane, Queensland.		Brisbane, Queensland.		Golf Course Fence		
Defects discovered			· ·			
· · ·		•				
· .						•
3. THE FLIGHT					······································	
Last or intended departure point	Time of departure	Next point of intended	landing Purpose of		Class of operation	
Tenterfield	1515	Departure Poir	t Famili	miliarisation Private		

THE CREW						
Name	Status	Age	Closs of licence	Hours on type	Total hours	Degree of injury
David Phillip ALLAN	Pilot	27	Commercial	20	338	Serious
OTHER DEPRONS (All				1		

5. OTHER PERSONS (All passengers and persons injured on ground)

Name	Status	Degree of injury	Name	Status	Degree of injury	
					•	
· · · · · · · · · · · · · · · · · · ·						
6. CONTRAVENTIONS OF RE	GULATIONS AND	ORDERS				
Regulation or Order No.	Nature of contravention ·					

A. N. R. 133(2)(b) The aircraft was flown at a height lower than 500 feet above the terrain.

RELEVANT EVENTS

The pilot took off for a local flight and shortly afterwards the aircraft was seen by witnesses on the ground flying at heights variously estimated at 40 to 300 feet above ground level. As the aircraft approached the western boundary of the Tenterfield Golf Course it was seen to enter a manoeuvre having some semblance to a stall turn or a partial loop. The aircraft did not recover from this manoeuvre and struck the ground in a steep nose down attitude.

8. OPINION AS TO CAUSE

The cause of the accident was that the pilot attempted an acrobatic manoeuvre at an unsafe height.

Report approved . Fockam .	(D.S. GRAHAM)	Designation Assistant Director-General (Air Safety Investigation)	Date 4.2.1971