1

Aviation Safety Investigation Report 199001975

Piper Aircraft Corp PA-32

9 April 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not formally investigated by the Bureau.

Occurrence Number: 199001975 Occurrence Type: Accident

Location: Batemans Bay NSW

Date: 9 April 1990 **Time:** 1744

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	5
Total	0	0	0	6

Aircraft Details: Piper Aircraft Corp PA-32

Registration: VH-PXG Serial Number: 32-40293 Operation Type: Private Damage Level: Substantial

Departure Point: Wollongong NSW

Departure Time: 1547 **Destination:** Orbost Vic

Approved for Release: 10th April 1991

Circumstances:

he pilot reported that he had obtained forecasts and actual weather reports for the intended route. The forecasts indicated low cloud, rain showers and drizzle along the coast, but actual reports indicated that he would get through. After waiting some time for the weather to improve, he departed, following shortly after another aircraft along the same route. In the Batemans Bay area he was unable to proceed further south, and found the weather closing in behind. After circling for some time, and with darkness approaching, he elected to carry out a precautionary landing on a beach. During the landing run, the aircraft struck patches of soft sand, resulting in the nose landing gear collapsing and right main gear being torn off.