

**Aviation Safety Investigation Report
198602634**

Aero Commander 690 A

03 January 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198602634
Location: Brisbane QLD
Date: 03 January 1986
Highest Injury Level: Nil
Injuries:

Occurrence Type: Accident

Time: N/K

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Aero Commander 690 A
Registration: VH-AAG
Serial Number:
Operation Type: Charter (Positioning)
Damage Level: Substantial
Departure Point: Moomba SA
Departure Time: N/K
Destination: Brisbane QLD

Approved for Release: August 20th 1986

Circumstances:

As the pilot was manoeuvring the aircraft prior to parking, the right wing tip area struck a steel fence corner-post. The post was bent and several strands of barbed wire were broken, as the wing rode over the post. The pilot was unaware that the aircraft had struck the post, and the damage to the aircraft was not reported until the following day.