1

Aviation Safety Investigation Report 198803512

Robinson R22 Beta

25 March 1988

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198803512 Occurrence Type: Accident

Location: Villadale (36km North of Richmond) QLD **Date:** 25 March 1988 **Time:** 1130

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Robinson R22 Beta

Registration: VH-HAP
Serial Number: Unknown
Operation Type: Aerial Work
Damage Level: Substantial
Departure Point: Villadale QLD

Departure Time: 0930

Destination: Villadale QLD

Approved for Release: 9th August 1989

Circumstances:

The pilot reported that while mustering cattle he was attempting to turn an animal that had broken away from the mob. During this procedure the pilot attempted to climb the helicopter over a line of trees, however, the main rotor blades struck the top of one of the trees. The helicopter was landed and an inspection found that the main rotor blades required replacement.

Significant Factors:

The following factors were considered relevant to the development of the accident

- 1. The pilot became distracted, from the task of flying the aircraft, while chasing the animal.
- 2. The pilot misjudged the clearance of the helicopter from the tree.