## 1

**Aviation Safety Investigation Report 199000080** 

Cessna C152-G

01 April 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not formally investigated by the Bureau.

Occurrence Number: 199000080 Occurrence Type: Accident

**Location:** Bounty Homestead WA

**Date:** 01 April 1990 **Time:** 1415

**Highest Injury Level:** Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	1
Total	0	0	0	2

Aircraft Details: Cessna C152-G

Registration: VH-KPS
Serial Number: 15066318
Operation Type: Private
Damage Level: Substantial

**Departure Point:** Bounty Homestead (6 km

South Lake King) WA

**Departure Time:** N/A

**Destination:** Bounty Homestead WA

**Approved for Release:** 10th May 1991

## **Circumstances:**

The pilot reported that he was attempting a practice glide approach onto a farm strip when during the final approach, he carried out a 360 degree turn to lose height. As a result of the turn the aircraft ended up low on the approach and although the pilot applied power to correct the glide path the aircraft touched down on a gravel road 115 metres short of the strip. The aircraft bounced, touched down in the rough alongside the road, collided with trees and came to a stop with a collapsed nosewheel.