Aviation Safety Investigation Report 198503517

Robinson R22A

22 June 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198503517 Occurrence Type: Accident

Location: 66 km SE of Charters Towers QLD

Date: 22 June 1985 **Time:** 1015 (Aprx)

Highest Injury Level: Serious

Injuries:

	Fatal	Serious	Minor	None
Crew	0	1	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	1	0	0

Aircraft Details: Robinson R22A

Registration: VH-HBL

Serial Number:

Operation Type: Private (Mustering)

Damage Level: Destroyed

Departure Point: St Pauls Station Homestead

oeparture romt. QLD

Departure Time: 1015 (Aprx)

St Pauls Station Homestead

Destination: OLD

Approved for Release: 31st January, 1986

Circumstances:

After helping to herd cattle to a yard, the pilot turned the helicopter and accelerated away adjacent to a creek. The helicopter struck a powerline, which crossed the creek at right angles, and impacted the ground on its right side. One of the main rotor blades bounced backwards into the cabin and almost severed the pilot's right foot. The powerline was difficult to see against the background of the surrounding countryside. The pilot, who has no memory of the accident, was aware of the location of the powerline but now believes he must have temporarily forgotten about its presence.