## **Aviation Safety Investigation Report 198800699**

Libelle H201

**24 January 1988** 

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198800699 Occurrence Type: Accident

**Location:** 5 km NE of Kalangadoo SA

**Date:** 24 January 1988 **Time:** 1515

Highest Injury Level: Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

**Aircraft Details:** Libelle H201 **Registration:** VH-GSQ **Serial Number:** 138

**Operation Type:** Private (Gliding) **Damage Level:** Substantial **Departure Point:** Millicent SA

**Departure Time:** N/K

**Destination:** Millicent SA

**Approved for Release:** 2 May 1988

## **Circumstances:**

The pilot was undertaking a cross-country flight, when a lack of thermal activity made an outlanding necessary. An open field was selected which appeared to the pilot to be covered with stubble. A normal approach was flown, but during the landing flare the right wing struck thistles which were about one metre high. The glider swung to the right and the fuselage was broken during the resulting ground loop. The accident was not the subject of an on-site investigation.