

**Aviation Safety Investigation Report
198500135**

Beech 95-D55

9 May 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198500135
Location: Dalwallinu WA
Date: 9 May 1985
Highest Injury Level: Nil
Injuries:

Occurrence Type: Accident

Time: 1545

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	5
Total	0	0	0	6

Aircraft Details: Beech 95-D55
Registration: VH-KNE
Serial Number:
Operation Type: Carriage of Passengers
Damage Level: Substantial
Departure Point: Carnamah WA
Departure Time: 1545
Destination: Dalwallinu WA

Approved for Release: 22nd August, 1985

Circumstances:

The aircraft was landed at the destination strip with the gear up. No fault was found with the aircraft or its systems that could have contributed to the accident. The pilot reported that he carried out the downwind and pre-landing checks, both of which included a gear check, but he could not explain why he did not lower the gear.