Aviation Safety Investigation Report 198702598

Cessna 310 R

28 March 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Number: Location: Date: Highest Injury Level: Injuries:		Merimbula NSW 28 March 1987			Occurrence Type: Incident Time: 1200	
ınjui ies.		Crew Ground Passenger Total	Fatal 0 0 0 0	Serious 0 0 0 0 0	Minor 0 0 0 0	None 0 - 0 0
Aircraft Details: Registration: Serial Number: Operation Type: Damage Level: Departure Point: Departure Time: Destination:	VH-FFA Aerial V (Demor Minor Merimb N/K	A Work astration)				

Approved for Release: June 2nd 1987

Circumstances:

The aircraft was engaged in a demonstration of the dropping of emergency equipment from low altitude over the sea. This demonstration was being performed for the benefit of television news media personnel. The emergency equipment was contained in a bag which was connected to the aircraft by a static line. On the particular dropping run, the static line became entangled in the spreader bars of a sea anchor which had been packed in the bag. The entanglement prevented the bag from being opened, and it then swung below the aircraft before rising, passing above the horizontal stabiliser and striking the side of the fin and rudder. The static line was cut by the Assistant Dropmaster and the bag fell free. The aircraft remained under control and a safe landing was subsequently carried out. There had been no provision made to secure the anchor spreader bars to prevent their inadvertent deployment. As there had been no other recorded instances of the bars fouling the static line, it was probable that the bag had been incorrectly packed. This may have been related to distractions caused by the film crew during the packing sequence. There had also been no provision made to prevent the static line from blowing behind the bag during the deployment sequence. During the investigation, the pilot claimed that an underlying cause of the incident was harassment by Department of Aviation officers. This harassment included lack of advice and assistance in the development of the emergency dropping equipment, together with unnecessary restrictions being placed on the operation. Detailed interviews conducted with the crew of the aircraft established that all members of the team performed normally on the day. There were no major procedural variations introduced for the particular demonstration, and the operation had been performed successfully in the past. An assessment of the evidence obtained concluded that the alleged harassment was not a factor in the incident.