

**Aviation Safety Investigation Report
199003133**

Drifter 582

30 November 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not formally investigated by the Bureau.

Occurrence Number: 199003133

Location: Boonah QLD

Date: 30 November 1990

Highest Injury Level: Minor

Injuries:

Occurrence Type: Accident

Time: 955

	Fatal	Serious	Minor	None
Crew	0	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	1	0

Aircraft Details: Drifter 582

Registration: N/A

Serial Number: 25-410

Operation Type: Sport Aviation

Damage Level: Substantial

Departure Point: Boonah QLD

Departure Time: N/K

Destination: Boonah QLD

Approved for Release: 13th February 1991

Circumstances:

While attempting to recover from a bounced landing, the pilot lost directional control of the aircraft and it collided with a fence.