

**Aviation Safety Investigation Report
198403579**

Stits SA6B

1 December 1984

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198403579

Occurrence Type: Accident

Location: Aldinga (38 km S Adelaide) SA

Date: 1 December 1984

Time: 1845

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	1
Total	0	0	0	2

Aircraft Details: Stits SA6B

Registration: VH-ULB

Serial Number:

Operation Type: Private - Pleasure

Damage Level: Substantial

Departure Point: Aldinga

Departure Time: N/A

Destination: Aldinga

Approved for Release: 24th January 1985

Circumstances:

After installing his passenger in the aircraft, the pilot hand swung the propeller, the normal means of starting the engine. When the engine fired it ran up to high power and the aircraft jumped the chocks. The pilot attempted to stop the aircraft but it continued forward and collided with the side of a hangar. The nose gear collapsed and the wooden propeller shattered as the aircraft came to rest on its nose. During the pre-start checks the pilot believes he set the throttle almost fully open by mistake. The aircraft handbrake was unservicable.