Aviation Safety Investigation Report 198502514

Beech C23

3 February 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Number: Location: Date: Highest Injury Level: Injuries:		Hoxton Park NSW 3 February 1985			Occurrence Type: Accident Time: 1005	
J			Fatal	Serious	Minor	None
		Crew	0	0	1	1
		Ground	0	0	0	-
		Passenger	0	0	0	0
		Total	0	0	0	1
Aircraft Details: Registration: Serial Number: Operation Type: Damage Level: Departure Point: Departure Time: Destination:	VH-UM Circuit Substan Hoxton N/A	IM Practice tial				

Approved for Release: 11th March 1985

Circumstances:

The pilot, who was inexperienced in total hours and hours on the aircraft type, landed the aircraft firmly. A bounce occurred but the pilot persevered with the landing. After the aircraft had bounced a further three times the nose wheel collapsed and the aircraft slid to rest on its nose.