



Australian Government

Australian Transport Safety Bureau

ATSB TRANSPORT SAFETY INVESTIGATION REPORT

Aviation Occurrence Report – 200501912

Final

Tower Shaft Failures on PWC Engines

Pratt and Whitney Canada

PW100 Series Engines

